

Part 573 Safety Recall Report

17V-470

Manufacturer Name : Temsa Global Sanayi Ve Ticaret A.S.

Submission Date : JUL 24, 2017

NHTSA Recall No. : 17V-470

Manufacturer Recall No. : NR



Manufacturer Information :

Population :

Manufacturer Name : Temsa Global Sanayi Ve Ticaret A.S.

Number of potentially involved : 184

Address : Temsa USA
5840 C South Semoran Blvd Orlando
FL 32822

Estimated percentage with defect : 100 %

Company phone : 4072718935

Vehicle Information :

Vehicle 1 : 2014-2018 TEMSA TS45

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Bus with stainless steel monocoque structure

Production Dates : NOV 01, 2013 - JUN 30, 2017

VIN Range 1 : Begin : NLTEJXU81E1000003 **End :** NLTEJXM81J1000187 Not sequential

Description of Defect :

Description of the Defect : The air bellow protection cover may be bended during operation or service of the vehicle. Under certain circumstances the bended or deformed air bellow protection cover may touch and damage the tag axle tires.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The air bellow protection cover may cause stuck or damage of tires or loose the control of vehicle while the vehicle is in motion potentially increasing the risk of crash.

Description of the Cause : The air bellow protection cover may be bended during operation or service of the vehicle.

Identification of Any Warning that can Occur : The defect can be identified by either; the tire inner surface damage on tag axle or deformed/bended air bellow cover

Supplier Identification :**Component Manufacturer**

Name : NR
Address : NR
NR
Country : NR

Chronology :

In June 2017, it is informed from the field that the bended or deformed air bellow protection cover may touch the tire on some vehicles. Temsa Engineering inspected this issue and after this evaluation, Temsa Safety Committee decided to conduct a voluntary safety recall

To date, no accidents, no injuries, no fatalities have been reported

Description of Remedy :

Description of Remedy Program : Technical service bulletin will be issued by Temsa and NHTSA will be informed with the service bulletin

How Remedy Component Differs from Recalled Component : The current and new covers are totally different and can be distinguished from each other

Identify How/When Recall Condition was Corrected in Production : The vehicle in the production will be using the new part

Recall Schedule :

Description of Recall Schedule : Temsa will inform the distributor. And Temsa will send notifications to customers after receiving approval by NHTSA for Temsa's draft owner notification letter

Planned Dealer Notification Date : JUL 26, 2017 - AUG 04, 2017

Planned Owner Notification Date : AUG 18, 2017 - SEP 14, 2017

* NR - Not Reported