Part 573 Safety Recall Report

Manufacturer Name :CSI Emergency Apparatus, LLCSubmission Date :AUG 02, 2017NHTSA Recall No. :17V-486Manufacturer Recall No. :NR



17V-486

Manufacturer Information :

Manufacturer Name : CSI Emergency Apparatus, LLC Address : 2332 Dupont Street Grayling MI 49738 Company phone : 348-2877

Population :

Number of potentially involved : 4 Estimated percentage with defect : 25 %

Vehicle Information :

Vehicle 1:	2013-2016 Ford F550
Vehicle Type :	BUSES, MEDIUM & HEAVY VEHICLES
Body Style :	PICKUP TRUCK
Power Train :	NR
Descriptive Information :	On certain Wildland Units with Stazworks wheels, the wheels should be inspected for cracks and possible breaks. Continued vehicle use may result in partial or complete loss of the wheel, which could cause damage to the chassis and/or other vehicles, and possibly result in a crash.
Production Dates :	MAR 07, 2013 - NOV 07, 2016
VIN Range 1:	Begin :NREnd :NRNot sequential

Description of Defect :

On certain Wildland Units with Stazworks wheels, the wheels should be inspected for cracks and possible breaks.
NR
NR
Continued vehicle use may result in partial or complete loss of the wheel, which could cause damage to the chassis and/or other vehicles, and possibly result in a crash.
NR
NR

Supplier Identification :

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Component Manufacturer	
Name : Stazworks, LLC	
Address : w8827 Chicadee Road	
Merrillan WISCONSIN 54	4754
Country : United States	
Chronology :	
malfunctioned where it connected to	tomer (May 23, 2017) that one of the wheels had failure and the wheel to the bolts. We inquired with the customer, took pictures and sent them to ed to just replace the wheels that were currently on the road, since there
Description of Remedy :	
	CSI has notified all customers that purchased wheels from that supplier that they should no longer operate the vehicles until the wheels have been replaced. CSI has replaces all of the potentially defective wheels with new wheels.
Description of Remedy Program : How Remedy Component Differs	that they should no longer operate the vehicles until the wheels have been replaced. CSI has replaces all of the potentially defective wheels with new
How Remedy Component Differs	that they should no longer operate the vehicles until the wheels have been replaced. CSI has replaces all of the potentially defective wheels with new wheels.CSI had the supplier manufacture new wheels with thicker structural rigidity and a new bold pattern that withstands greater pressure.
Description of Remedy Program : How Remedy Component Differs from Recalled Component : Identify How/When Recall Condition was Corrected in Production :	that they should no longer operate the vehicles until the wheels have been replaced. CSI has replaces all of the potentially defective wheels with new wheels.CSI had the supplier manufacture new wheels with thicker structural rigidity and a new bold pattern that withstands greater pressure.
Description of Remedy Program : How Remedy Component Differs from Recalled Component : Identify How/When Recall Condition was Corrected in Production : Recall Schedule :	that they should no longer operate the vehicles until the wheels have been replaced. CSI has replaces all of the potentially defective wheels with new wheels. CSI had the supplier manufacture new wheels with thicker structural rigidity and a new bold pattern that withstands greater pressure. NR The recall started by notifying the effected customers around June 16, 2017 that we would be replacing all of the potentially effected wheels.
Description of Remedy Program : How Remedy Component Differs from Recalled Component : Identify How/When Recall Condition was Corrected in Production : Recall Schedule :	that they should no longer operate the vehicles until the wheels have been replaced. CSI has replaces all of the potentially defective wheels with new wheels. CSI had the supplier manufacture new wheels with thicker structural rigidity and a new bold pattern that withstands greater pressure. NR The recall started by notifying the effected customers around June 16, 2017 that we would be replacing all of the potentially effected wheels We had replaced all of the potentially effected wheels by July 31, 2017

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573