

# Part 573 Safety Recall Report

# 17V-566

**Manufacturer Name :** Halcore Group, Inc.

**Submission Date :** SEP 13, 2017

**NHTSA Recall No. :** 17V-566

**Manufacturer Recall No. :** 17E-038



## Manufacturer Information :

**Manufacturer Name :** Halcore Group, Inc.

**Address :** 3800 McDowell Road

Grove City OH 43123

**Company phone :** 999

## Population :

**Number of potentially involved :** 4

**Estimated percentage with defect :** 100 %

## Vehicle Information :

**Vehicle 1 :** 2016-2017 American Emergency Vehicl Type III Traumahawk

**Vehicle Type :** BUSES, MEDIUM & HEAVY VEHICLES

**Body Style :**

**Power Train :** NR

**Descriptive Information :** Per TriMark Recall17E-038 the Striker pins/bolts for ambulance door produced between a window of time had a manufacturing defect. Replacement pins meet strength requirement.

**Production Dates :** MAY 01, 2017 - JUN 23, 2017

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

## Description of Defect :

**Description of the Defect :** AEV's supplier / vendor - TriMark Corporation (TriMark) is recalling certain door striker bolts, model number 070-0100 (RECALL# 17E-038), assembled into door systems for ambulance manufacturers and distributors. The striker bolts may fail under load allowing the doors to open in the event of a crash. As such, these bolts fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 206, "Door locks and door retention components."

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** If a door opens in a crash there would be an increased risk of injury.

**Description of the Cause :** Vendor supplied door striker pin. Reference TriMark Recall 17E-038.

**Identification of Any Warning that can Occur :** None

**Supplier Identification :****Component Manufacturer**

Name : TriMark Corporation  
Address : 500 Bailey Ave  
New Hampton IOWA 50659  
Country : United States

**Chronology :**

TriMark notified AEV of an issue concerning striker pins installed on modular body pre-assemblies & individual striker pin inventory received. Effected time frame with a buffer was determined to be 5/1/2017 thru 6/23/2017.

**Description of Remedy :**

Description of Remedy Program : TriMark & AEV will notify the purchasers of the door systems, and will provide replacement Striker Bolts, free of charge. Owners may contact Trimark customer service at 1-641-394-3188 or AEV at 1-800-374-9749 Warranty Department. TriMark to reimburse direct upon completion of verification card.

How Remedy Component Differs from Recalled Component : TriMark Corporation (TriMark) is recalling certain door striker bolts, model number 070-0100.

Identify How/When Recall Condition was Corrected in Production : Referencing TriMark Recall 17E-038. TriMark notified AEV of an issue concerning striker pins installed on modular body pre-assemblies & individual striker pin inventory received. Effected time frame with a buffer was determined to be 5/1/2017 thru 6/23/2017. AEV technicians exchanged the (on hand) Modular body striker pins prior to end user delivery. 4 modular bodies on chassis were already delivered to customers.

**Recall Schedule :**

Description of Recall Schedule : NR  
Planned Dealer Notification Date : SEP 29, 2017 - OCT 31, 2017  
Planned Owner Notification Date : SEP 29, 2017 - OCT 31, 2017

\* NR - Not Reported