

Part 573 Safety Recall Report

17V-682

Manufacturer Name : Indian Motorcycle Company**Submission Date :** DEC 12, 2017**NHTSA Recall No. :** 17V-682**Manufacturer Recall No. :** I-17-03**Manufacturer Information :**

Manufacturer Name : Indian Motorcycle Company

Address : 2100 Highway 55

Medina MN 55340

Company phone : 999

Population :

Number of potentially involved : 2,096

Estimated percentage with defect : 1 %

Vehicle Information :

Vehicle 1 : 2017-2018 Indian CHIEF / CHIEF CLASSIC / CHIEF DARK HORSE / CHIEF VINTAGE / CHIEFTAIN / CHIEFTAIN CLASSIC / CHIEFTAIN DARK HORSE / CHIEFTAIN ELITE / CHIEFTAIN LIMITED / SPRINGFIELD / SPRINGFIELD DARK HORSE

Vehicle Type : MOTORCYCLES

Body Style : ALL

Power Train : GAS

Descriptive Information : Motorcycles equipped with halogen headlights may have been manufactured using a non-compliant headlight during final assembly. Affected motorcycles, designated for sale in the US, may be equipped with an E4 (European) headlight assembly and are not considered compliant per NHTSA (FMVSS 108). The E4 headlight has different photometric and marking requirements which must be inspected and, if necessary, replaced with the correct headlight.

Production Dates : APR 05, 2017 - AUG 16, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : Motorcycles equipped with halogen headlights may have been manufactured using a non-compliant headlight during final assembly. Affected motorcycles, designated for sale in the US, may be equipped with an E4 (European) headlight assembly and are not considered compliant per NHTSA (FMVSS 108). The E4 headlight has different photometric and marking requirements which must be inspected and, if necessary, replaced with the correct headlight.

FMVSS 1 : 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2 : NR

Description of the Safety Risk : Does not comply with NHTSA (FMVSS 108) standards

Description of the Cause : The manufacturer of the headlight shipped mislabeled parts.

Identification of Any Warning NR
that can Occur :

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

During a parts sort at the manufacturing facility, it was discovered that some of the headlights for production were mislabeled and replaced with the EU variant of the headlight.

Description of Remedy :

Description of Remedy Program : Indian Motorcycle will issue a Service Bulletin to all Indian Motorcycle dealers, with instructions required to inspect and replace the headlight assembly as necessary. Repairs will be made by any authorized Indian Motorcycle dealer at no cost to you. The actual inspection / installation should take less than one hour to perform; however, it may take longer due to service scheduling requirements.

How Remedy Component Differs from Recalled Component : The US headlight is marked with "SAE", whereas the European headlight is marked with "E4".

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Dealers were contacted to inspect the affected units in stock, while the owners were contacted with instructions on how to inspect and identify parts that are not compliant with US standards.
Planned Dealer Notification Date : NOV 02, 2017 - NOV 03, 2017
Planned Owner Notification Date : DEC 06, 2017 - DEC 07, 2017

* NR - Not Reported