

Part 573 Safety Recall Report

17V-684

Manufacturer Name : East Manufacturing Corp.

Submission Date : OCT 27, 2017

NHTSA Recall No. : 17V-684

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : East Manufacturing Corp.

Address : 1871 State Route #44

P.O. BOX 277 Randolph OH 44265

Company phone : 330-325-9921

Population :

Number of potentially involved : 573

Estimated percentage with defect : 1 %

Vehicle Information :

Vehicle 1 : 2013-2018 Frameless Dump Hybrid

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : VIN#'s involved were built after a design change to the bolster area above the draft arm tubing/landing gear dolly location.

Production Dates : JAN 01, 2013 -OCT 26, 2017

VIN Range 1 :Begin : 1e1j9u289er049496 **End :** 1e1j9u284jr062912

☒ Not sequential

Description of Defect :

Description of the Defect : Cracks may develop on bottom of draft arm tubing at rear side of rear most dolly brace bracket

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Cracks an spread across the bottom of the draft arm tubing, then up the sides of the draft arm tubing until a failure of the draft arm tubing occurs

Description of the Cause : NR

Identification of Any Warning that can Occur : Cracks may develop on bottom of draft arm tubing at rear side of rear most dolly brace bracket

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR
NR
Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs NR
from Recalled Component :

Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported