

Part 573 Safety Recall Report

17V-725

Manufacturer Name : Honda (American Honda Motor Co.)**Submission Date :** MAR 06, 2018**NHTSA Recall No. :** 17V-725**Manufacturer Recall No. :** POQ**Manufacturer Information :**

Manufacturer Name : Honda (American Honda Motor Co.)

Address : 1919 Torrance Blvd.

Torrance CA 90501

Company phone : 1-888-234-2138

Population :

Number of potentially involved : 806,936

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2012-2012 Honda Odyssey

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records. The VIN range reflects all possible vehicles that could potentially experience the problem.

All 2011-2017 model year Odyssey vehicles are being recalled. Prior and later model year Odyssey vehicles have different second row seat attachment mechanisms.

Production Dates : AUG 23, 2011 - SEP 12, 2012

VIN Range 1 : Begin : 5FNRL5H44CB001001 End : 5FNRL5H46CB148159 Not sequentialVIN Range 2 : Begin : 5FNRL5H40CB039311 End : 5FNRL5H67CB140427 Not sequential

Vehicle 2 : 2011-2011 Honda Odyssey

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records. The VIN range reflects all possible vehicles that could potentially experience the problem.

All 2011-2017 model year Odyssey vehicles are being recalled. Prior and later model year Odyssey vehicles have different second row seat attachment mechanisms.

Production Dates : MAR 02, 2010 - SEP 22, 2011

VIN Range 1 : Begin : 5FNRL5H97BB000001 End : 5FNRL5H6XBB500126 Not sequentialVIN Range 2 : Begin : 5FNRL5H66BB019418 End : 5FNRL5H66BB089601 Not sequentialVIN Range 3 : Begin : 5KBRL5868BB700004 End : 5KBRL5860BB900002 Not sequential

Vehicle 3 : 2013-2013 Honda Odyssey

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records. The VIN range reflects all possible vehicles that could potentially experience the problem.

All 2011-2017 model year Odyssey vehicles are being recalled. Prior and later model year Odyssey vehicles have different second row seat attachment mechanisms.

Production Dates : AUG 28, 2012 - JUN 07, 2013

VIN Range 1 : Begin : 5FNRL5H24DB001001 End : 5FNRL5H68DB092311 Not sequential

VIN Range 2 : Begin : 5FNRL5H62DB001372 End : 5FNRL5H64DB076882 Not sequential

Vehicle 4 : 2014-2014 Honda Odyssey

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records. The VIN range reflects all possible vehicles that could potentially experience the problem.

All 2011-2017 model year Odyssey vehicles are being recalled. Prior and later model year Odyssey vehicles have different second row seat attachment mechanisms.

Production Dates : MAY 28, 2013 - SEP 08, 2014

VIN Range 1 : Begin : 5FNRL5H96EB001001 End : 5FNRL5H40EB139671 Not sequential

VIN Range 2 : Begin : 5FNRL5H62EB001275 End : 5FNRL5H61EB121181 Not sequential

Vehicle 5 : 2015-2015 Honda Odyssey

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records. The VIN range reflects all possible vehicles that could potentially experience the problem.

All 2011-2017 model year Odyssey vehicles are being recalled. Prior and later model year Odyssey vehicles have different second row seat attachment mechanisms.

Production Dates : JUL 31, 2014 - AUG 06, 2015

VIN Range 1 : Begin : 5FNRL5H49FB001001 End : 5FNRL5H67FB132140 Not sequential

VIN Range 2 : Begin : 5FNRL5H68FB013156 End : 5FNRL5H46FB120558 Not sequential

Vehicle 6 : 2016-2016 Honda Odyssey

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records. The VIN range reflects all possible vehicles that could potentially experience the problem.

All 2011-2017 model year Odyssey vehicles are being recalled. Prior and later model year Odyssey vehicles have different second row seat attachment mechanisms.

Production Dates : JUL 14, 2015 - DEC 20, 2016

VIN Range 1 : Begin : 5FNRL5H38GB001001 End : 5FNRL5H38GB169835 Not sequential

VIN Range 2 : Begin : 5FNRL5H6XGB001379 End : 5FNRL5H40GB149426 Not sequential

Vehicle 7 : 2017-2017 Honda Odyssey

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records. The VIN range reflects all possible vehicles that could potentially experience the problem.

All 2011-2017 model year Odyssey vehicles are being recalled. Prior and later model year Odyssey vehicles have different second row seat attachment mechanisms.

Production Dates : DEC 20, 2016 - APR 13, 2017

VIN Range 1 : Begin : 5FNRL5H69HB000001 End : 5FNRL5H45HB027131 Not sequential

VIN Range 2 : Begin : 5FNRL5H40HB001262 End : 5FNRL5H66HB020769 Not sequential

Description of Defect :

Description of the Defect : The second row outboard (outer) seats can be placed in two positions, standard and wide. The rear outboard seat strikers have a collar to define the two set positions. If an outboard seat is positioned over the collar while attaching the seat to the vehicle floor, the seat will not latch properly to the seat striker.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : An unlatched second row outboard seat could tip forward during moderate to heavy braking increasing the risk of injury to an occupant, including a child seated in a LATCH child seat.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

Please refer to the attached document titled 'Chronology.pdf' for the original chronology.

3/6/2018 Amendment

Nov. 2017 – March 2018

Honda continued to investigate remedy solutions, developed a final countermeasure bracket, designed a new second row seat garnish warning label which will include instructions on how to properly install the seat and confirm it is locked and updated the owner's information card for the second row outboard seats.

March 6, 2018

Honda has determined a final remedy and is amending the Defect Information Report to provide updated information.

As of March 6, 2018, Honda has received 6 warranty claims, 2 field reports, and 48 minor injuries related to this issue.

Description of Remedy :

Description of Remedy Program : Registered owners of affected vehicles will receive a notification letter in the mail that will contain detailed instructions for installing/positioning second row outer seats and confirming that they are securely latched. Similar information will be provided via online and social media channels prior to the notification. Once a final remedy is determined and the necessary parts are available, Honda will send a second letter to registered owners asking them to bring their vehicles to a dealership for a free repair.

3/6/2018 Amendment

Registered owners of all affected vehicles will be contacted by mail and asked to take their vehicle to a Honda automobile dealer. The dealer will install a bracket to the second row forward outboard floor strikers to prevent improper seat positioning, apply a warning label to the second row outboard seats and provide an updated owner's information card for free.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Owners will be notified by mail on or about December 28, 2017.

3/6/2018 Amendment

The estimated date to start notification to dealers: March 7, 2018

The estimated date to start notifications to owners: March 26, 2018

Planned Dealer Notification Date : NOV 18, 2017 - NR

Planned Owner Notification Date : DEC 28, 2017 - NR

* NR - Not Reported