

Part 573 Safety Recall Report

17V-779

Manufacturer Name : Travel Lite Rv

Submission Date : DEC 06, 2017

NHTSA Recall No. : 17V-779

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Travel Lite Rv

Address : 71319 CR 23
New Paris IN 46553

Company phone : 8313000

Population :

Number of potentially involved : 163

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2018 Travel Lite Rv F-23 TH & F-23 RB

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Lippert Components found that they installed the wrong hitch coupler on the frame from the Travel Lite F-23Th and F-23RB. The hitch that was installed is a 2" Class III hitch coupler and it should have been a 2 5/16" Class III hitch coupler.

Production Dates : APR 03, 2017 - NOV 17, 2017

VIN Range 1 : Begin : NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : Lippert Components found that they installed the wrong hitch coupler on the frame from the Travel Lite F-23Th and F-23RB. The hitch that was installed is a 2" Class III hitch coupler and it should have been a 2 5/16" Class III hitch coupler.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Because the coupler is under rated for the weight of the GVWR for the trailer the trailer could become unhitched from the tow vehicle

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs NR
from Recalled Component :

Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported