

# Part 573 Safety Recall Report

# 17V-827

**Manufacturer Name :** Keystone RV Company**Submission Date :** DEC 19, 2017**NHTSA Recall No. :** 17V-827**Manufacturer Recall No. :** 17-310**Manufacturer Information :**

Manufacturer Name : Keystone RV Company

Address : PO Box 2000  
2642 Hackberry Drive Goshen IN  
46527

Company phone : 574-535-2100

**Population :**

Number of potentially involved : 12

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2018-2018 Keystone Hideout Model 303

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Model 303

Production Dates : OCT 24, 2017 - NOV 22, 2017

VIN Range 1 : Begin : 4YDF30327J7246791 End : 4YDF30321J7247810  Not sequential**Description of Noncompliance :**

**Description of the Noncompliance :** It has been decided that the vehicles in this recall population fail to conform to the requirements of Part 567, "Certification." The vehicles subject to this recall may have been manufactured with the incorrect information on the Federal Identification Tag. The tag indicates the GAWR as 5080 LB. The correct GAWR is 5200 LB; the tires are listed as ST225/75R15D and should be ST225/75R15E; and PSI 65 should be 80.

FMVSS 1 : 567 - Certification

FMVSS 2 : NR

**Description of the Safety Risk :** Fails to conform to the requirements of Part 567, "Certification."**Description of the Cause :** The incorrect information was printed on the label.

**Identification of Any Warning that can Occur :** The GAWR printed on the Federal Identification Tag does not match the GAWR printed on the axle tag and tire load range on the tag does not match tire load range on the tires.

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

## Chronology :

December 11, 2017 – Production noted the label was incorrect.

December 18, 2017 – Investigation concluded and determined the Federal Identification Tag would need to be replaced.

## Description of Remedy :

Description of Remedy Program : The remedy is to replace the Federal Identification Tag.

How Remedy Component Differs from Recalled Component : The repair will conform to requirements of Part 567, "Certification."

Identify How/When Recall Condition was Corrected in Production : Units were quarantined, inspected then repaired as indicated by inspection.

## Recall Schedule :

Description of Recall Schedule : Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA. procedures.

Planned Dealer Notification Date : DEC 29, 2017 - DEC 29, 2017

Planned Owner Notification Date : DEC 29, 2017 - DEC 29, 2017

\* NR - Not Reported