

Part 573 Safety Recall Report

17V-842

Manufacturer Name : Hyundai Translead

Submission Date : JAN 11, 2018

NHTSA Recall No. : 17V-842

Manufacturer Recall No. : 17E049



Manufacturer Information :

Manufacturer Name : Hyundai Translead

Address : 8880 Rio San Diego Drive, #500
San Diego CA 92108-164

Company phone : 819-574-1500

Population :

Number of potentially involved : 259

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2017-2017 Hyundai Translead 30012130, 30012400, 30012409, 30012410, 30012431, 30012434, 30012481 & 30012595

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Trailer Axles & MPA/MTA Suspensions found to have caliper bolts that did not meet torque specifications.

Production Dates : JUN 01, 2017 - AUG 31, 2017

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : Trailer Axles & MPA/MTA Suspensions found to have caliper bolts that did not meet torque specifications. The suspected axles and suspensions were assembled at the Meritor Frankfort site.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If caliper bolts are not torqued properly it could lead to a brake failure which may cause an accident.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Meritor
Address : NR
NR
Country : United States

Chronology :

Trailer Axles & MPA/MTA Suspensions found to have caliper bolts that did not meet torque specifications. The suspected axles and suspensions were assembled at the Meritor Frankfort site.

Description of Remedy :

Description of Remedy Program :	Replacement parts are currently available and if needed will be provided by Meritor at no cost. Also, technical service bulletin to inspect and tighten carrier mounting bolts has been made available.
How Remedy Component Differs from Recalled Component :	A caliper bolt that is properly torqued will function normally. A caliper bolt that is not torqued to spec may lead into a brake failure and cause an accident.
Identify How/When Recall Condition was Corrected in Production :	NR

Recall Schedule :

Description of Recall Schedule :	Hyundai will send a notification to the (2) customers affected by this recall (Transervice and Trailer Equipment) once the notification is approved by NHTSA. The notification letters were submitted 1/11/2018.
Planned Dealer Notification Date :	JAN 12, 2018 - JAN 12, 2018
Planned Owner Notification Date :	JAN 12, 2018 - JAN 12, 2018

* NR - Not Reported