



---

June 7, 2018

**Subject: Transition for Passenger Air Bag Inflator Replacement - Affecting Safety Recalls 9416E, 0617A, and 2018A**

**Attention: Mazda Dealer Principal, and Service, and Parts Managers**

Please be advised Mazda is preparing to transition Recalls 9416E, 0617A, and 2018A to a new permanent remedy inflator. **The part numbers affected by this action are GLYA-57-K80 and F1Z1-57-K80.**

To prepare for the new inflator kits, parts ordering for Recalls 9416E, 0617A, and 2018A will close on Tuesday, June 12<sup>th</sup> at 5:00 PM PST, and any outstanding repairs for these recalls should be completed by Friday, June 15<sup>th</sup>.

During the weeks of June 18<sup>th</sup> to June 29<sup>th</sup> Mazda, along with the hazmat specialist, Shipmate, will work with your dealership to collect all your on hand inventory for part numbers **GLYA-57-K80 and F1Z1-57-K80.**

On June 29, 2018, Mazda will launch a new recall using the new permanent remedy replacement inflators. It is important to note the permanent remedy replacement inflator will involve a new inflator type that contains a counter-measure improvement, and will use new part numbers.

In the event you have a request to complete a customer repair during the transition, Mazda recommends usage of an MCVP loaner vehicle when available. If all MCVP vehicles are in use, or unavailable, then use your local rental facility; please offer a free rental car.

**On Friday, June 15<sup>th</sup> you will receive additional emails providing the full details of the parts collection process, including the timing to complete outstanding Warranty claims.**

Thank you for your cooperation.

Regards,

Technical Services & Parts Operations Division

---