



ABOVE & BEYOND

NOTIFICATION OF SAFETY RECALL P082 (NHTSA # 17V015): TAKATA PASSENGER AIRBAGS

SERVICE BULLETIN

17-FEB-17

NO.: SRE17-02

SEC.: RECALL

MKT.: USA

Jaguar Land Rover North America, LLC has informed the National Highway Traffic Safety Administration (NHTSA) of its intent to perform a voluntary Safety Recall on certain 2007–2009 and 2012 model year Land Rover Range Rover vehicles imported into the United States market. Information relating to this Recall will be posted on the National Highway Traffic Safety Administration website.

United States Federal regulations require that retailers must be notified within a reasonable time after the manufacturer decides that a defect that relates to motor vehicle safety or a noncompliance exists.

United States Federal law requires retailers to complete any outstanding safety Recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a retailer could result in a civil penalty of up to \$21,000.00 per vehicle.

This Recall Service Bulletin serves as notification to all Land Rover retailers in the United States that any affected new vehicles may not be sold and delivered for customer use until the Recall repair is completed.

DESCRIPTION OF ISSUE

An issue has been identified on certain vehicles listed within the Affected Vehicle Range. These vehicles are fitted with certain airbag inflators assembled as part of the front passenger airbag modules, and used as original equipment or replacement equipment.

AFFECTED VEHICLE RANGE

NOTE: refer to the appendix for the list of states and territories by Zone.

Certain 2012 model year Land Rover Range Rover vehicles originally sold, or ever registered, in 'Zone A.'

Unless included in 'Zone A' above, certain 2009 model year Land Rover Range Rover vehicles originally sold, or ever registered, in 'Zone B.'

Additionally, certain 2007–2008 model year Land Rover Range Rover vehicles originally sold, or ever registered, in 'Zone C'.

Range Rover (L322)

Model Year: 2007–2009

VIN: SALMF15497A239092-SALME15469A306625

Model Year: 2012

VIN: SALMP1E4XCA345963-SALMF1E45CA393633

A total of 8,711 vehicles are potentially involved in the USA and Federalized Territories as listed in the Appendix.

EFFECT ON VEHICLE OPERATION

In the event of a crash necessitating deployment of the front passenger airbag, these inflators may rupture due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling. An inflator rupture may result in metal fragments striking the vehicle occupants, resulting in serious injury or death.

SERVICE PROGRAM / REWORK ACTION

Jaguar Land Rover is currently sourcing replacement parts for this Recall. Parts are expected to be available during quarter 3, 2017. A Technical Bulletin will be published to TOPIx once a service repair is available. At that time, owners will be notified by mail to take their vehicle to a Land Rover retailer who will replace the front passenger airbag module.

There will be no charge to owners for this action.

OWNER NOTIFICATION

Owners will receive an interim notification by mail on or before 03 March 2017. They will receive a further notification by mail once a service repair is available. Parts are expected to be available during quarter 3, 2017.

ACTION TO BE TAKEN

Check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action.

Retailers are required to **HOLD** affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the rework action. Jaguar Land Rover North America recommends that affected sales demonstrator and loaner vehicles are repaired before use and that used vehicles are repaired before sale.

Sold vehicles will be subject to the standard Recall notification and Recall bulletin process detailing the action required for vehicles in the hands of owners.

A Technical Bulletin will be published once repair instructions are finalised and all required parts have been procured.

Thank you for your cooperation in this matter. Jaguar Land Rover North America apologizes for any inconvenience this may cause.

SAFETY RECALL P082: APPENDIX

ZONE 'A' STATES AND TERRITORIES:

Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, The Northern Mariana Islands (Saipan), The U.S. Virgin Islands

ZONE 'B' STATES:

Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, West Virginia

ZONE 'C' STATES:

Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, Wyoming