

**Subarunet Announcement**



**To: All Subaru Retailers**  
**From: Subaru of America, Inc.**  
**Date: August 2, 2018**

**UPDATE: Takata Recalls Front Passenger Air Bag Inflator Owner Renotifications**

As we work through the Takata recall process, we will continue to mail owner re-notification letters to urge additional customers to schedule an appointment for the repair. This notification process is being prioritized in phases, based on parts supply, age of the inflator in the vehicle (oldest first), and geographic registration history of the vehicle.

This month's owner renotification letters will include the following affected vehicles, based on recently refreshed owner information from IHS (Polk):

- TKA16 – 2003-2004 Legacy and Outback, 2003-2005 Baja, 2010-2011 Legacy and Outback, 2006-2009 Impreza and WRX, 2009-2010 Forester
- TKB16 – 2003-2004 Legacy and Outback, 2003-2005 Baja
- TKC16 – 2003-2004 Legacy and Outback, 2003-2005 Baja
- TKA17 – 2005-2006 Baja, 2010-2012 Legacy and Outback, 2009-2012 Forester
- TKB17 – 2005-2006 Baja, 2006-2009 Impreza and WRX, 2009 Forester
- TKC17 – 2005-2006 Baja, 2006-2008 Impreza and WRX

Approximately 202,800 renotifications will be mailed, nationally. Refreshed affected VIN lists will be distributed to each Region/Zone Office, which include the latest owner registration data for all open Takata recalls.

As always, please be sure to review the latest version of the Product Campaign Bulletin as found on STIS for the installation instructions and detailed parts information.

Thank you.