



# Parts Bulletin

TITLE:

**Recall R89714: Inflatable Curtain Bolts  
Model Year 2017 XC90, S90, V90CC, V90**

<b>GROUP:</b> 88	<b>CAT/NO:</b> R89714	<b>REFERENCE BULLETINS:</b> QB-R89714, TJ-32467	<b>CAR MARKET:</b> United States and Canada	
<b>COPY TO / CIRCULATIONS (PLEASE INITIAL):</b>			<b>ISSUE DATE:</b> 2017-03-15	<b>STATUS DATE:</b> 2017-03-15
<b>GENERAL MANAGER</b>	<b>PARTS MANAGER</b>	<b>SERVICE MANAGER</b>	<b>SALES MANAGER</b>	
				<b>Page 1 of 1</b>

**“Right first time in Time”**

**Reference Bulletins: QB-R89714, TJ-32467**

Volvo Car USA LLC and Volvo Car Canada LTD (Volvo) on behalf of Volvo Car Group has decided to launch Recall R89714 on certain model year 2017 XC90, S90, V90CC and V90 vehicles.

Due to a manufacturing error in the surface treatment process, the bolts that were used to assemble the inflatable curtain (IC) airbag may not meet specifications. This could result in one or more of the bolts breaking within 48 hours of installation, which in the event of a crash warranting deployment of the IC airbag, could increase the risk of injury to vehicle occupants.

The correction action is for Volvo retailers to replace all the inflatable curtain bolts.

A total of 10,476 U.S. and 1,209 Canadian vehicles are eligible for this recall.

The following part number applies:

Part Number	Description	Qty
30622999 *	Inflatable Curtain Bolt	As needed

**\* Bolt Allocations**

- An initial allocation of 30 bolts was processed on February 23, 2017
- A second allocation of 24 bolts was processed on March 10, 2017
- Another allocation of bolts will be processed on March 16, 2017. At this time we will allocate bolts for the remaining vehicles in retailer inventory.
- Information on additional bolt allocations and ordering procedures will be announced on Thursday, March 16.