

McLaughlin Boring Systems

Greenville, SC 29605 USA



SERVICE BULLETIN # VSB 154

DATE:

2-23-2017

Machine/Option:

Serial Numbers Involved: See attached

VX50-800 GEN 3

VX30-800 GEN 3

Subject: Mandatory Bulletin to be performed immediately to add trailer reinforcement to side rails and include past bulletins.

Background: To reduce deflection in trailer side rails and tongue area.

Solution: Add support to side rails and incorporate bulletins VSB/VIK150,151 and 152

For Reference:	<u>Primary Part Number(s)</u> MOD0012	<u>For Model(s)</u> VX50-800 GEN 3 And VX30-800 GEN 3
-----------------------	---	---

Priority:	Completion Schedule:
<input checked="" type="checkbox"/> Mandatory	<input type="checkbox"/> 30 days from date of this bulletin
<input type="checkbox"/> Recommended	<input type="checkbox"/> 90 days from date of this bulletin
<input type="checkbox"/> Information only	<input type="checkbox"/> 180 days from date of this bulletin
	<input type="checkbox"/> Only Units within Standard Limited Warranty Period
	<input checked="" type="checkbox"/> Product Safety Alert: Install immediately
	<input type="checkbox"/> N/A
Dealer Distribution:	Reimbursement:
<input checked="" type="checkbox"/> Domestic	<input type="checkbox"/> Only Units within Standard Limited Warranty Period
<input type="checkbox"/> International	<input checked="" type="checkbox"/> Product Safety Alert: Work Completion Certificate Required
<input type="checkbox"/> Both	<input checked="" type="checkbox"/> All Serial Numbers Listed Above
	<input checked="" type="checkbox"/> Parts <input checked="" type="checkbox"/> Labor Paid(Labor Code: 12 HR)
	<input type="checkbox"/> No Reimbursement

Due to the inconvenience of this bulletin for customers Mclaughlin will cover one standard normal service for each unit listed on the bulletin. Parts for the service that will be covered are oil filter part #T700077, fuel filter part #8090544-07, fuel water separator part #8090941-01, and proper quantity of oil. All parts will need to be ordered from Mclaughlin. Oil will come from dealers inventory.

The process to cover will be to submit a warranty claim for the above parts and proper quantity of oil used along with 2 Hours of labor. Note on the claim for VSB154 service.