

TOL NOTICE (US) – November 13, 2017

**SAFETY RECALL ACTION NOTICE 552:
Speed Triple Regulator/Rectifier Link Lead Replacement**

Triumph Motorcycles is issuing **Safety Recall Action Notice 552**. Please visit the Service Bulletin Library located in Triumphonline.net (TOL) to access Service Bulletin 552 or refer to the attached copy. Internal investigations have identified a need to replace the regulator/rectifier link lead. Dealers are required to replace and reroute the regulator/rectifier link lead as described within the attached **Safety Recall Action Notice 552**. Dealers can also download **Safety Recall Action Notice 552** on **Triumph Online > Service/Technical > Service Bulletins**.

We require your immediate attention to rectify the below affected machines:

Safety Recall Action Notice 552	
Models Affected	U.S. VIN Range
Speed Triple R	from 738052 to 795114
Speed Triple S	from 738052 to 795114

Stop delivery of affected motorcycles immediately. DO NOT deliver a motorcycle affected by this Safety Recall Action Notice to a customer until you have completed, or confirmed completion of, the procedures described in this Safety Recall Action Notice.

Delivering a motorcycle subject to an outstanding Safety Recall Action Notice may contravene local or national laws in your market, territory or country. Triumph subsidiaries and distributors must instigate a Safety Recall Action in their country in accordance with the national recall code of practice.

For vehicles in dealer stock, the safety recall MUST be actioned before delivery to the customer. Dealers should quarantine any unsold or uncollected machines and arrange their modification prior to any further deliveries. You may wish to use TOL to assist you identify unsold stock. Dealers are to prioritize repair of customer owned motorcycles before any unsold motorcycles.

TRIUMPH MOTORCYCLES AMERICA

Please Note:

- Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory.
- The modified motorcycles can be identified by checking the “Outstanding Service Bulletins” on Warranty Online.

Warranty Claim Instructions

Bulletin Number	Fault Code	Repair Code	Description	Repair Time Allowance
552	2507392	99552	Renew regulator/rectifier link lead	0.75 hours

Genuine Parts Information

Notice Number	Part Number	Description	Quantity
552	T2500954	Link Lead Regulator	1

Consult the attached PDF or download Service Bulletin 552 on TOL for complete instructions. Please ensure that your staff is aware of this action and that all relevant staff download, read and circulate the above mentioned **Safety Recall Action Notice 552**. If you have any questions regarding this safety recall, contact Triumph 24/7 Customer Support immediately at (888) 284-6288.

TRIUMPH MOTORCYCLES AMERICA