

IMPORTANT CAMPAIGN INFORMATION

ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager

Freightliner Dealers – U.S. and Canada

Western Star and Sterling Dealers – U.S. and Canada

FCCC Dealers – U.S. and Canada

Daimler Trucks North America LLC

WARRANTY CAMPAIGNS DEPARTMENT

P.O. Box 4090

800-547-0712

Portland, Oregon 97208-4090

FAX 503-745-9009

REF #: ICI17-036
Effective: 12/11/2017
Release: 12/11/2017

If you have questions about this Letter, please submit your inquiry on the Web using the [WSC Link on DTNAConnect](#)

SUBJECT: TBB FL753 – Interim Recall Notice

This letter is to inform you that an interim recall notice is being issued for Thomas Built Buses recall FL753, TBB IMMI Seat Belt Buckle Rods. It will mail before the end of the year. The recall affects a small group of vehicles in the United States.

A copy follows for your reference.

This notice is for your information only. There is no action for customers or dealers to take at this time. If customers inquire, please let them know the recall will begin when all preparations are complete.

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through the WSC Link on DTNAConnect.

The information contained in this letter supercedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.

Daimler Trucks North America LLC

Daimler Trucks North America LLC
Thomas Built Buses
1408 Courtesy Road
High Point, NC 27260
336.889.4871 Phone

December 2017
FL753
Interim Recall Notice
NHTSA #17V-729

IMPORTANT SAFETY RECALL

See enclosed VIN list

Subject: TBB IMMI Seat Belt Buckle Rods

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Daimler Trucks North America LLC, on behalf of its wholly owned subsidiary, Thomas Built Buses, Inc., has decided that a defect which relates to motor vehicle safety exists on specific Saf-T-Liner C2, HDX, and EFX school buses and Minotour DRW and SRW school buses manufactured November 23, 2015, through June 15, 2016.

On certain buses, the IMMI seat belt assemblies equipped with 3-point lap and shoulder belts fail to comply with the requirements of S4.2 of Federal Motor Vehicle Safety Standard (FMVSS) 210 S4.2 – Seat Belt Assembly Anchorages, Strength. The seats may have a buckle mount rod that may fracture in the event of a crash, increasing the risk of injury.

Seat belt buckle rods will be replaced on affected seats.

This is the first of two notices you will receive regarding this subject. This letter is to inform you of an upcoming Recall to correct the issue noted above. Parts are not yet available. You may continue to operate your vehicle.

The second notice will inform you when the final remedy is available. **When you receive the second notice**, please contact your authorized Thomas Built Buses dealer to schedule the Recall for your vehicle.

If you do not own the vehicle that corresponds to the identification number(s), which appears on the Recall Notification, please return the notification to the Warranty Campaigns Department with any information you can furnish that will assist us in locating the present owner.

We apologize for any inconvenience this may have caused. If you have any questions or require further information, please contact the Warranty Department at (336) 889-4871, 8:00 a.m. to 5:00 p.m. Eastern Time, Monday through Friday. You may wish to submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590; or call the Vehicle Safety Hotline at (888) 327-4236 (TTY: 800-424-9153); or to <http://www.safercar.gov>.

THOMAS BUILT BUSES WARRANTY DEPARTMENT
Enclosures