



TECHNICAL SERVICE BULLETIN

Reference Number: 06-04-21-001
Date of Issue: November 17, 2017
Affected Model: Bluecar

SERVICE INFORMATION

Software error which inserts the incorrect bias value when a missing sensor condition exists in combination with the Bluecar requested calibration can lead to an inadvertent deployment or crash record issue.

To eliminate this risk a new software (62P version) has been developed by the supplier. This software needs to be integrated in every vehicle at the airbag ECU level. This operation will be performed by the supplier with a reflash of the ECU, assisted by a BlueIndy technician to prepare the access to the connector. This operation lasts not more than 15 minutes

A record of the operations shall be performed to track the reflash of every vehicle

Procedure

Do this	Don't do this
Use updated software version 62P	Don't use software version 62B