

**IMPORTANT Update to T79 and U11 Safety Recall**By **Mopar** on Friday, February 16, 2018

FEBRUARY 2018

**IMPORTANT UPDATE TO T79 AND U11 SAFETY RECALL****BRAKE TRANSMISSION SHIFT INTERLOCK 2017 - 2018 RAM TRUCK**

This communication is meant to notify all US dealers of the immediate removal of the service procedure and software flash for U11 and T79 Safety Recall (Brake Transmission Shift Interlock - BTSI) on Ram 1500, 2500, 3500, 4500, and 5500.

*The recall will remain in place on these vehicles, but the service procedure will be removed temporarily. Please review the below important information.*

**T79 AND U11 SERVICE REPAIR TEMPORARY REMOVAL**

On 2/15/18, FCA released the repair procedure and software flash for 2017 MY vehicles impacted by the T79 recall and 2017 & 2018 MY vehicles impacted by U11 recalls (Brake Transmission Shift Interlock - BTSI). This software flash may have caused some vehicles to experience issues such as an ABS light illuminated after vehicle start up or locked doors.

To ensure vehicles are safely remedied, the recall will remain open on vehicles impacted, but the Repair Instructions and Software flash will ***not*** be available while the software receives further validation to correct the issue.

**Any unsold vehicle that has already received the software flash should NOT be sold. Customer owned vehicles that have already received this software flash will be contacted by FCA at a later date to ensure the vehicle receives the final remedy.**

FCA apologizes for this inconvenience and is working hard to correct the concern. Service Instructions and software will be available as soon as the concern has been rectified.

More information will be communicated as soon as possible. Thank you.