



Indian Motorcycle Company
P.O. Box 47700
Medina, MN 55340-9960

IMPORTANT SAFETY RECALL This notice applies to your vehicle

Recall Campaign: 17V682
Subject: 2017-18 Indian Motorcycles (111 c.i.)
Headlight Lens Inspection / Replacement
PLEASE READ IMMEDIATELY

VIN I-17-03

FIRST NAME LAST NAME
ADDRESS
CITY, ST ZIP

Dear Indian Motorcycle Owner:

Indian Motorcycle has determined that motorcycles may have been manufactured with a headlight that does not comply with the Federal Motor Vehicle Safety Standards. Our records indicate that you have purchased a motorcycle that may be affected.


The reason for this notice:

Motorcycles equipped with halogen headlights may have been manufactured using a non-compliant headlight during final assembly. Motorcycles, distributed for sale in North America, may be equipped with an E4 (European) headlight assembly which do not comply with the applicable Federal Motor Vehicle Safety Standards. The E4 headlight has different photometric and marking requirements which must be inspected and, if necessary, replaced with the FMVSS compliant headlight.

What you should do:

Contact your Indian Motorcycle dealer to schedule an inspection; or if you prefer, inspect the headlight on your motorcycle for the markings indicated below.

1. Look at the center headlight from the front of the motorcycle. In the 4 o'clock position, the letters "**SAE**" must be visible.
 - If you have the correct headlight, **no further action is required.**
 - If you have an incorrect headlight, contact your authorized Indian Motorcycle dealer to schedule an appointment to have the bulletin repair performed. Do not attempt repairs yourself. Repairs must be done only by an authorized Indian Motorcycle dealer.



What Indian Motorcycle and your dealer will do:

Indian Motorcycle has issued a Safety *Bulletin* to all Indian Motorcycle dealers, with instructions required to inspect and replace the headlight assembly, as needed. Repairs will be made by any authorized Indian Motorcycle dealer at no cost to you. The actual inspection / installation should take less than one hour to perform; however, it may take longer due to service scheduling requirements.

If you have questions or if you need more information:

While your Indian Motorcycle dealer is in the best position to answer your questions, if you have any questions that your dealer cannot address, if you are having difficulty obtaining the repair outlined in this letter, or if you need assistance finding an Indian Motorcycle dealer, please visit the web site at <http://www.indianmotorcycle.com> or contact our Indian Motorcycle Consumer Service Department by calling 1-877-204-3697.

This notice was mailed to you according to our most current registration information. If you no longer own your Indian motorcycle, please contact your local Indian Motorcycle dealer to have the ownership information changed. The Indian Motorcycle Consumer Service Department cannot change ownership information without identification. Federal law requires that any vehicle lessor receiving this notice must forward a copy of this notice to the lessee within 10 days.

Please accept our apologies for any inconvenience this may cause you. Your safety and continued satisfaction with your Indian Motorcycle is our primary concern. Thank you for your prompt attention to this matter.

Sincerely,
Indian Motorcycle Company