

# Rear Impact Guard Inspection



**Issue Overview:** This inspection covers specific model years of 2015 and 2016 for the Walker TTT with a 54" tandem setting. There is a potential for cracks to develop in the rear impact guards (Fig 1-3). Specific locations of the welded brackets require inspection until units can be repaired.



Figure 1



Figure 2



Figure 3

Cracks in rear impact guard




Figure 4

Arrows indicate areas of inspection

**Inspection:** Inspect the welded bracket(s) for cracks (Fig 4). Rear impact guards with cracks need addressed ASAP.

**Next Steps:** A bumper modification bulletin is available and the Warranty group is working on a list of service providers who can perform it. For any questions, please contact the Warranty group at 608-562-7813.