



INSTRUCTIONS TO PERFORM RECALL CAMPAIGN 144

Models Affected:

- Certain 2016 and 2017 model year Winnebago Travato[®], Models 259G and 259K, motorhomes.

These motorhomes were manufactured from April 17, 2015 through January 24, 2017.

Tools Required:

- Screw Gun (Phillips)

Procedure:

- Ensure there is adequate clearance between the park brake rod and park brake cable.

NOTE: *The vehicle will need to be elevated to visually inspect the LP hose.*

1. Visually inspect the LP hose for clearance. If adjustment is needed, loosen the adjustment clamp and move LP hose to ensure the hose is not coming in contact with the park brake rod and park brake cable. The hose should not touch anything other than the rubberized clamp.
2. Replace the LP hose if any damage is noticed. Contact Part Sales at 1-800-556-9670 to order a replacement LP hose.

