



Thor Motor Coach Recall Repair Instructions

Recall # 17V-238

Description/Title: **Rim Size Typographical error on Fed Tag**

Affected Product Line(s): **Certain 2017 Palazzo Motorhomes**

Service Campaign # : **RC000133** Released Date: **5/17/2017**

Failure Code: **TMCRC80462V** Document Date: **5/17/2017**

Time Allowed: **0.1** Document Revision: **A**

Issue: There is a typographical error on the Federal ID Tag with regards to the size of the tire rim.

Parts Needed: New Federal ID Tag (“tag”) TMC Item number: 0394305

- 1. Locate the existing tag. It can be found at, or directly behind, the Driver’s Seat. The incorrect tag is pictured below.**

MANUFACTURED BY: THOR MOTOR COACH, INC.		Offline: 3/17	
GVWR: 12701 KG(28000 LB)		SERIAL:	
INC. VEH. MFG. BY: FREIGHTLINER CUSTOM CHASSIS		MODEL:	
GAWR KG(LB)	TIRES	RIMS	COLD INFLATION PRESSURE
FRONT: 4763 (10500)	255/70R22.5	22.x8.25	827 KPA(120 PSI)
REAR: 7938 (17500)	255/70R22.5	22.5x8.25	827 KPA(120PSI)
TAG:			SINGLE <input checked="" type="checkbox"/> DUAL <input type="checkbox"/>
THIS VEHICLE CONFORMS TO ALL APPLICABLE U.S. FEDERAL MOTOR VEHICLE SAFETY STANDARDS IN EFFECT IN 01/17			
V.I.N.:		MULTIPURPOSE TYPE: PASSENGER VEHICLE	

- 2. Make sure the existing tag is free of dirt, debris, or any other substance that might interfere with the adhesive on the new tag.**

- 3. Apply the new tag over the existing tag.**