

May 5, 2017

06404 Version 1

Safety Recall: 2015–16 CR-V Replacement Engine Short Block Out of Specification

AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2016	Pilot	ALL	Check the iN VIN status for eligibility (fewer than 20 vehicles are affected)

BACKGROUND

A small number of replacement engine blocks may have been manufactured with the incorrect pistons. In a small number of cases (fewer than 20) where an original engine was already replaced in a vehicle, a direct injection engine block may have been replaced with an engine block with pistons designed for regular port injection. An engine block with the incorrect pistons installed may result in the MIL coming on or may result in engine damage.

This bulletin will be revised in the future once the repair procedure, parts information, and warranty claim information are available.

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by “do-it-yourselfers,” and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.