



Thor Motor Coach Recall Repair Instructions

Recall # 17V-381

Description/Title: **2018 Outlaw Awning Light Fuse Size**

Affected Product Line(s): **Certain 2018 Outlaw 29H Motorhomes**

Service Campaign # : **RC000143**

Released Date: **7/28/2017**

Failure Code: **TMCRC80466V**

Document Date: **7/28/2017**

Time Allowed: **0.2**

Document Revision: **A**

Issue: On certain 2018 Outlaw 29H motorhomes a 15 amp fuse may have been incorrectly used for the awning lights. The correct size fuse is 2 amps.

Parts required: 2 amp blade fuse - TMC Item number: 0100778

Instructions:

To inspect and replace the fuse for the awning lights, you will need to access the Rapid Camp fuse panel. On the 29H the fuse panel is located behind the converter and underneath the cabinet drawers at the passenger's side rear of motorhome (Figure 1).

NOTE: Take care when completing this repair. Thor Motor Coach will not cover damage incurred to the unit that occurs during the process of completing this repair.

Figure 1



