

Safety Recall: 2013–16 Accord Battery Management Sensor**AFFECTED VEHICLES**

Year	Model	Trim	VIN Range
2013–16	Accord	ALL	Check the iN VIN status for eligibility

BACKGROUND

The case for the battery sensor mounted at the top of the 12V battery may have been improperly manufactured with gaps that could allow for moisture entry. If moisture containing road salt, or other conductive substances, enters the battery sensor, it could result in an electrical short and, subsequently, a fire. Refrain from calling Tech Line for updates.

Check for an iN message for further details.

This bulletin will be updated once Parts Information, Warranty Claim Information, Inspection Procedures, and Repair Procedures are available.

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by “do-it-yourselfers,” and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.