



Thor Motor Coach Recall Repair Instructions

Recall #	17V-544	TC #	2017-419
Description/Title:	Iota ITS-50R Transfer Switch—Expanded Scope		
Affected Product Line(s):	2010-2011 Hurricane 2011 Serrano 2011 Windsport		
Service Campaign # :	RC000145	Released Date:	September 2017
Failure Code:	TMCRC80442Y—Inspect TMCRC80442V—Replace	Document Date:	September 2017
Time Allowed:	.2 Inspect & 1.0 Replace	Document Revision:	A

SUMMARY: All of the motorhomes subject to this recall campaign are equipped with an Iota ITS-50R transfer switch which may be experiencing heat related failure when exposed to elevated electrical loads associated with RV use in higher ambient temperatures. The connections at the buss bar inside of the switch are not adequate resulting in elevated operating temperatures.

PARTS REQUIRED: ATS-50 Transfer Switch—TMC Part Number: 0255378

INSTRUCTIONS:

1. Verify the motorhome has the Iota ITS-50R transfer switch installed. If it has already been replaced by another brand, no further action is necessary.
2. Replace the transfer switch. Make sure all connections are properly secured.