



Service Bulletin

American Honda Motor Co., Inc.

CBR1000RR #9
ISSUED: October 2017

SAFETY and EMISSION RECALL

2017 CBR1000RR/RA/S1/S2 - FUEL CAP ASSEMBLY REPLACEMENT

Interim bulletin, a complete bulletin will be available in the near future.

AFFECTED UNITS

2017 CBR1000RR/RA	All
2017 CBR1000S1/S2	All

PARTS INFORMATION

All dealers with affected inventory will automatically be shipped parts to repair all units in their inventory in the near future.

BACKGROUND

Honda is launching a SAFETY and EMISSION RECALL of all model year 2017 CBR1000RR/RA/S1/S2 motorcycles to replace the fuel cap assembly. If the fuel cap seal swells, a gap may occur between the fuel tank cap seal and the fuel filler neck. The gap may allow water to enter the gas tank from the outside. If water enters the tank it may cause engine stalling.

Safety Consequence

An engine stall could result in the loss of power and may increase the risk of a crash.

CUSTOMER NOTIFICATION

American Honda is sending a letter to owners of 2017 model year CBR1000RR/RA/S1/S2 motorcycles informing them that their motorcycle is being recalled for a safety and emission related defect. AHM intends to mail customer letters as early as possible, subject to regulatory agency approval.

DEALER INVENTORY

Effective October 26, YOU MUST NOT SELL any NEW or USED 2017 CBR1000RR/RA/S1/S2 until it is repaired according to this bulletin.

- To search for applicable recalls on a specific unit, use *Unit Information* on **iN**.
- To manage your affected inventory, use *eResponsibility Report* on **iN**.

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your Honda. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your Honda, or that your Honda has the condition described. To determine whether this information applies, contact an authorized Honda dealer.