



February, 2019

*** * * IMPORTANT SAFETY RECALL REMINDER * * ***

According to our records, your 2015 Transit has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **17S15 - Driveshaft Flexible Coupling Replacement**

What is the issue? On your vehicle, the driveshaft flexible coupling may crack with increasing mileage, resulting in driveline noise and vibration. Continued driving with a cracked flexible coupling may cause separation of the driveshaft.

Separation of the driveshaft can result in a loss of motive power while driving, or unintended vehicle movement in park without the parking brake applied. In addition, separation of the driveshaft can result in secondary damage to surrounding components, including brake and fuel lines. A driveshaft separation may increase the risk of injury or crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: www.Fordowner.com.

Thank you for your attention to this very important matter.

Febrero de, 2019

*** * * RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD * * ***

SegUR nuestros registros, no se realizaron en sur 2015 Transit las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **17S15 - Reemplazo del acoplamiento flexible de la flecha de mando**

¿Cuál es el problema? El acoplamiento flexible de la flecha de mando de su vehículo corre el riesgo de agrietarse en la medida que aumenta el millaje, lo cual se podría traducir en ruido y vibración del eje propulsor. Si continúa manejando con el acoplamiento flexible agrietado se podría producir la separación de la flecha de mando.

La separación de la flecha de mando podría ocasionar la pérdida de la potencia motriz mientras maneja o un movimiento accidental del vehículo mientras está en estacionamiento sin el freno de estacionamiento accionado. Adicionalmente, la separación de la flecha de mando podría producir un daño secundario en los componentes de los alrededores, incluidas las tuberías de frenos y de combustible. La separación de la flecha de mando podría aumentar el riesgo de sufrir lesiones o un choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: www.Fordowner.com.

Gracias por su atenciic en este asunto sumamente importante.

1 of 2

000000000000001



P. O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

A / / 0000000000000001 / A



4

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

