

**NOTE: UNREPAIRED VEHICLES IN RECALLS 9416E, 0617A AND 2018A HAVE BEEN SUPERSEDED TO RECALL 2618F**

**CONDITION OF CONCERN**

In the subject vehicles, continued exposure to high levels of absolute humidity may cause the passenger frontal air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the passenger frontal air bag. An inflator rupture could result in metal fragments striking the front passenger or other vehicle occupants, resulting in serious injury or death.

Dealers are to replace the passenger side frontal air bag inflator of subject vehicles with a permanent remedy one.

**MANDATORY AIR BAG INFLATOR RETURN**

The original air bag inflator(s) should be returned by your dealership every 30 days or once 200 inflators have been accumulated. All inflator part numbers can be counted and shipped together for these returns. To schedule a return, please contact XPO at (877) 650-3476. Detailed air bag inflator return instructions can be found on MGSS and the Dealer Assistance Group websites. Failure to return the original inflator will result in a Warranty Claim Debit.

**SUBJECT VEHICLES**

**Zone B**

Model	VIN Range	Note
2009 RX-8	ALL	Originally sold or ever registered in Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, West Virginia

**Zone C**

Model	VIN Range	Note
<del>2005-2006 MPV</del>	<del>ALL</del>	Originally sold or ever registered in Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, Wyoming
2005-2008 RX-8	ALL	

**OWNER NOTIFICATION**

Mazda will notify U.S. owners by first class mail beginning **March 9, 2017**.

**PARTS INFORMATION**

Description	Part Number	Quantity	Applicable Model
Passenger Side Front Air Bag Inflator	<del>GLYA-57-K80</del>	<del>4</del>	<del>MPV</del>
	F1Z1-57-K80	1	RX-8
Campaign Label	9999-95-065A-06	1=50 labels	<i>Obtain in MStore (no charge)</i>

**WARRANTY CLAIM PROCESSING INFORMATION**

	Replacement of Passenger Side Front Air Bag Inflator	
	<del>MPV</del>	RX-8
Warranty Type	<del>R</del>	R
Process Number	<del>AH009A</del>	AH009B
Symptom Code	<del>99</del>	99
Damage Code	<del>99</del>	99
Part Number Main	<del>GLYA-57-K80</del>	F1Z1-57-K80
Quantity	<del>4</del>	1
Labor Operation Number	<del>XXN2LXRX</del>	XXN2LXRX
Labor Hours	<del>0.5 hrs.</del>	0.4 hrs.

**RENTAL CAR INFORMATION**

Mazda recommends the usage of the MCVP loaner vehicle when available. If all MCVP loaner vehicles are in use and unavailable, and the customer needs a rental car, then use your local rental facility and offer a rental car. Be sure that every effort is made to repair the car within one business day or less in order to allow the next customer the same experience.

**Rental Car Warranty Claim Information**

	<b>MCVP Vehicle Preferred</b>	<b>Rental Agency Vehicle</b>
Warranty Type Code	N/A MCVP does not require claim submission	<b>A</b>
Symptom Code		99
Damage Code		99
Part Number Main Cause		<b>5555-06-17AR</b>
Part Quantity		0
Labor Operation Code		MM024XRX
Labor Hours		0
Sublet – Rental Car		
Sublet Invoice Number		Number from Rental Invoice or Dealer Purchase Order
Sublet Type Code		Enter "Z9" (other)
Sublet Amount		Up to \$30.00 per day for the number of days customer had rental car
Sublet Text		Number of days rental car was supplied to customer

Rental expenses exceeding the two-day limit will require prior DSM Authorization, as outlined in the Mazda Rental Car Reimbursement Program policy.