

## HYUNDAI RECALL 159 – SANTA FE SPORT TPMS NONCOMPLIANCE - CHRONOLOGY

Kia Motor Manufacturing Georgia and its supplier initiated a joint investigation upon receiving warranty return parts of tire pressure sensors. The investigation, which took place in the fall of 2016, concluded that in certain circumstances, when tire pressure sensors were installed (as part of the wheel and tire assembly) the sensor may have been inadvertently set in the incorrect mode. If this occurs, the sensor will not be able to transmit the tire pressure signal, and the (TPMS) warning light in the instrument cluster will illuminate within 20 minutes when the vehicle's ignition is in the "on" position. On February 2, 2017 KMMG shared a draft TSB with Hyundai Motor America (HMA), and subsequently provided HMA with a list of potentially affected VINs on February 9, 2017. HMA verified the VIN list and reviewed for any related TPMS related repairs at dealers. Upon further review of the issue, on February 28, 2017, Hyundai decided to conduct a noncompliance recall for the affected 2017 Model Year Santa Fe Sport vehicles.

Hyundai is not aware of any accidents or injuries related to this condition.