



ENTEGRA
COACH®

RECALL CAMPAIGN

NHTSA# 17V-441
TC# 2017-348

Date of Publication July 2017

Affects Spartan motor home chassis equipped with a Cummins ISX 15 engine. The drive gear on the fuel pump may spin loose on the drive shaft, resulting in loss of pumping function. If this occurs, the engine may stall without warning and cannot be restarted.

Spartan Service Centers/Cummins Distributor will replace the fuel pump free of charge.
To locate the nearest Spartan Service Center/Cummins distributor to set appointment,
Please contact **Spartan Motors Customer Product Support Group @ 1-855-589-9836.**

AFFECTED UNITS

2018 Cornerstone Class A Motor Homes
J16A8051
J16B8051-8060, 8067
J16W8051-8052, 8054-8055
J16X8051-8053
J16Y8052
J16W8053