

CONDITION OF CONCERN

In certain vehicles with continued exposure to high levels of humidity over long periods, the driver air bag inflator could produce excessive internal pressure in the event of a crash where the front air bag is designed to deploy. The excessive internal pressure may cause the inflator housing to rupture with metal fragments, which may increase the risk of injury to the vehicle occupants.

Dealers are to replace the driver side frontal air bag inflator with a new Permanent remedy inflator.

Note: Some vehicles in this recall are also included in Safety Recall 9416E, which applies to passenger air bag inflator replacement.

MANDATORY AIR BAG INFLATOR RETURN

The original air bag inflator(s) should be returned by your dealership every 30 days or once 200 inflators have been accumulated. All inflator part numbers can be counted and shipped together for these returns. To schedule a return, please contact XPO at (877) 650-3476. Detailed air bag inflator return instructions are provided in Attachment IV, and can also be found on MS3 and the Dealer Assistance Group website. Failure to return the original inflator will result in a Warranty Claim Debit.

SUBJECT VEHICLES

Model	VIN Range
2004-2008 RX-8	All
2003-2008 Mazda6	All
2006-2007 Mazdaspeed6	All

OWNER NOTIFICATION

Affected vehicles will be notified in September 2017

PARTS INFORMATION

Description	Part Number	Quantity	Notes
Driver Side Front Air Bag Inflator	F1Z4-57-K80	1	RX-8
	GLYC-57-K80	1	Mazda6, Mazdaspeed6
Campaign Label	9999-95-065A-06	1=50 labels	Obtain in Mazda e-Store (no charge)

PARTS ORDERING

All parts are available for normal ordering. Please use VIN inquiry on eMDCS to confirm the vehicle is involved in the recall and in OPEN status for recall 1417G.

Warranty Information - Recall 1417G

	Replacement of Driver Side Front Air Bag Inflator	
	Mazda6 / Mazdaspeed6	RX-8
Process Number	AH035A	AH035B
Symptom Code	99	99
Damage Code	99	99
Part Number Main Cause	GLYC-57-K80	F1Z4-57-K80
Quantity	1	1
Labor Operation Number	XXN7WXRX	XXN7WXRX
Labor Hours	0.3 hrs.	0.3 hrs.

RENTAL CAR INFORMATION

Mazda recommends the usage of the MCVP loaner vehicle when available. If all MCVP loaner vehicles are in use and unavailable, and the customer needs a rental car, then use your local rental facility and offer a rental car. Be sure that every effort is made to repair the car within one business day or less in order to allow the next customer the same experience.

Rental Car Warranty Claim Information

	MCVP Vehicle Preferred	Rental Agency Vehicle
Warranty Type Code	N/A MCVP does not require claim submission	A
Symptom Code		99
Damage Code		99
Part Number Main Cause		5555-14-17GR
Part Quantity		0
Labor Operation Code		MM024XRX
Labor Hours		0
Sublet – Rental Car		
Sublet Invoice Number		Number from Rental Invoice or Dealer Purchase Order
Sublet Type Code		Enter "Z9" (other)
Sublet Amount		Up to \$30.00 per day for the number of days customer had rental car
Sublet Text		Number of days rental car was supplied to customer

Rental expenses exceeding the two-day limit will require prior DSM Authorization, as outlined in the Mazda Rental Car Reimbursement Program policy.

REPAIR PROCEDURE

Please refer to the repair procedure posted on MGSS