

September 7, 2017

## AMENDED NONCOMPLIANCE INFORMATION REPORT (17V548)

This supplements Toyota's Part 573 Report of August 31, 2017 concerning the driver/front passenger airbag assembly on certain Toyota Land Cruiser, Lexus LX470, and Lexus LX570 vehicles.

The information in the Identification of Involved Vehicles and Affected Components section is revised as noted below:

### Identification of Involved Vehicles and Affected Components:

Based on production records, we have determined the involved vehicle population to be the vehicles listed in the table below.

Make/Car Line	Model Year	Manufacturer	Production Period
Toyota Land Cruiser	2008 - 2016	TMC	September 4, 2007 – November, 12, 2015
Lexus LX470	2006	TMC	May 7, 2005 – October 27, 2005
Lexus LX570	2008 - 2013	TMC	July 13, 2007 – February 26, 2013

### VINs of involved vehicles

Make/Car Line	VIN
Toyota Land Cruiser	JTMHY05J084000131, JTMHY05J184000123, JTMHY05J984000533, JTMHY05J884000569, JTMHY05J184000509, JTMHY7AJ7F4028665, JTMCY7AJ1G4039317, JTMCY7AJ9G4039307
Lexus LX470	JTJHT00W564003120, JTJHT00W564005207, JTJHT00W264010736
Lexus LX570	JTJHY00W984000113, JTJHY00W184000770, JTJHY00W884015007, JTJHY00W794023102, JTJHY00W394024005, JTJHY00W294028644, JTJHY00W594028623, JTJHY00W394028541, JTJHY7AX6B4060373, JTJHY7AX8D4119605