

UPDATE APRIL 12, 2024, updated inflator part number

CONDITION OF CONCERN

In the subject vehicles, continued exposure to high levels of absolute humidity may cause the driver's and/or passenger's frontal air bag inflator to explode in the event of a crash. **An air bag inflator explosion could result in metal fragments striking the driver or other vehicle occupants, resulting in serious injury or death. It is extremely important to schedule this repair as soon as possible, to ensure your safety and the safety of your passengers.**

The vehicle may have had temporary air bag inflators installed under Safety Recalls 9116A and/or 8315F. However, both the driver and passenger PERMANENT remedy inflators must be replaced on all customer vehicles at the same time.

SUBJECT VEHICLES: These are the same vehicles subject to Safety Recall 1917L.

Model	VIN range	Build Date Range
2004-2006 B-Series Truck	ALL (except vehicles included in 2318A)	April 17, 2003 through May 2, 2006

OWNER NOTIFICATION: Mazda notified U.S. owners January 17, 2018.

MANDATORY AIR BAG INFLATOR RETURN: All inflator part numbers can be counted and shipped together for these returns. To schedule a return, please follow instructions on MGSS under this campaign or through the Dealer Assistance Group website.

PARTS INFORMATION

Description	Part Number	Quantity	Notes	Scrap
Passenger Frontal Air Bag Inflator	1FT1-57-K50C	1	Permanent Repair	No, see return info above
Campaign Label	9999-95-065A-06	1 pack = 50 labels	Obtain in Mazda e-Store (no charge)	N/A

WARRANTY CLAIM PROCESSING INFORMATION



Do not process this claim without the correct photo attachments as the claim will not be paid with the incorrect repair, missing RO in frame, or not clear. Make sure the technician gives you (warranty administrator) the correct photo.

Recall 1817L – PAB “Permanent” Repair	Replacement of Passenger Frontal Air Bag Inflator
Applicable Model	B-Series
Warranty Type	R
Process Number	J1802A
Symptom Code	99
Damage Code	99
Part Number Main Cause & Quantity	1FT1-57-K50C / 1 pc
Labor Operation Number	YY793XRX
Labor Hours	0.7 hrs.
Attachment ID: D40	Photo from repair Step 14, Correctly installed inflator and Repair Order showing the VIN in the same Photo
Attachment ID: D01	Repair Order

RENTAL CAR INFORMATION: PLEASE CLAIM ANY RENTALS ON RECALL 1917L