

U.S. Department of Transportation

National Highway Traffic Safety Administration

April 5, 2018

Mr. Colm Byrne Director of Procurement & Quality Timoney Technology IDA Technology Park Johnstown Navan C15 PX45

Subject: Front Axle Spindle may Fracture

Dear Mr. Byrne:

This letter serves to acknowledge Timoney Technology's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

1200 New Jersey Avenue SE Washington, DC 20590

NEF-150MR

18E-017

Makes/Models/Model Years:

TIMONEY/IFS GEN 2/9999 TIMONEY/IFS MARK I/9999

Mfr's Report Date: March 29, 2018

NHTSA Campaign Number: 18E-017

Components:

SUSPENSION: FRONT

Potential Number of Units Affected: 146

Problem Description:

Timoney Technology (Timoney) is recalling certain Mark 1 and Gen 2 Independent Front Suspensions (IFS). Inconsistent machining may result in fatigue cracks developing over time in the front axle spindles, causing failure of the spindle and the possible separation of a front wheel from the vehicle.

Consequence:

If a wheel separates from the vehicle, it can increase the risk of a crash.

Remedy:

Timoney will notify the vehicle manufacturers that purchased the affected suspensions, and those manufacturers will conduct recalls of their own with their dealers replacing the front axle spindle, free of charge. The recall is expected to begin April 27, 2018.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Please be reminded of the following requirements:

You are required to submit a draft purchaser notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

