



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

August 1, 2018

Ms. Natalia Medley
Regulatory Counsel
TRW Automotive Inc
12001 Tech Center Drive
Livonia, MI 48150

NEF-150MR
18E-048

Subject: Ball Joint Supplied with Incorrect Attachment Nut

Dear Ms. Medley:

This letter serves to acknowledge TRW Automotive Inc's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

TRW/BALL JOINT/9999

Mfr's Report Date: June 26, 2018

NHTSA Campaign Number: 18E-048

Components:

STEERING

Potential Number of Units Affected: 310

Problem Description:

TRW Automotive Inc (TRW) is recalling certain aftermarket replacement Ball Joints, part number JBJ343. These ball joints have attachments nuts that are the incorrect size, possibly causing a loss of steering control.

Consequence:

A loss of steering control can increase the risk of a crash.

Remedy:

TRW will notify the known purchasers and owners, and reimburse them for the returned ball joints, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact TRW customer service at 1-248-863-2437.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please provide a list of the known distributors that sold the affected parts.

Please provide a list of the known vehicle models that the affected parts could be used on.

Please be reminded of the following requirements:

You are required to submit a draft purchaser notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement