

January 16, 2018

Mr. David Robertson Group Manager, Environmental, Safety and Powertrain Engineering Mazda North American Operations 1025 Connecticut Ave, NW Washington, DC 20036

Subject: Driver Side Air Bag Inflator May Explode

Dear Mr. Robertson:

This letter serves to acknowledge Mazda North American Operations's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: MAZDA/B-SERIES TRUCK/2006

Mfr's Report Date: January 16, 2018

NHTSA Campaign Number: 18V-038

Components: AIR BAGS:FRONTAL:DRIVER SIDE INFLATOR MODULE

Potential Number of Units Affected: 160

Problem Description:

Mazda North American Operations (Mazda) is recalling certain 2006 B-Series vehicles. Upon deployment of the driver side frontal air bag, excessive internal pressure may cause the inflator to explode.

Consequence:

In the event of a crash necessitating deployment of the driver's frontal air bag, the inflator could explode with sharp metal fragments striking the vehicle occupants, potentially resulting in serious injury or death.

Remedy:

Mazda will notify owners instructing them to not drive their vehicles, and dealers will replace the front driver side air bag inflator with an alternate inflator, free of charge. The recall is expected to begin January 19, 2018. Owners may contact Mazda customer service at 1-800-222-5500. Mazda's number for this recall is 2218A.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150JK 18V-038

We have received Mazda's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian Chief, Recall Management Division Office of Defects Investigations Enforcement

