

U.S. Department of Transportation

National Highway Traffic Safety Administration

December 21, 2018

Mr. Chris Sandvig Volkswagen Group of America, Inc. 3800 Hamlin Road Auburn Hills, MI 48326 1200 New Jersey Avenue SE Washington, DC 20590

NEF-150SS 18V-862

Subject: Improperly Inserted Auxiliary Heater Connector

Dear Mr. Sandvig:

This letter serves to acknowledge Volkswagen Group of America, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

# Makes/Models/Model Years:

AUDI/A6/2015-2016 AUDI/A7/2015

**Mfr's Report Date:** December 5, 2018

NHTSA Campaign Number: 18V-862

# **Components:**

ELECTRICAL SYSTEM:WIRING

Potential Number of Units Affected: 845

### **Problem Description:**

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2015-2016 Audi A6 Sedans and 2015 Audi A7 vehicles. The auxiliary heater connector may not have been properly inserted into the auxiliary heater.

### **Consequence:**

If the auxiliary heater connector was not properly inserted, the connector may overheat, increasing the risk of a fire.

# Remedy:

Audi will notify owners, and dealers will inspect the auxiliary heater electrical connection, replacing the auxiliary heater and the connector, as necessary, free of charge. The recall is expected to begin February 1, 2019. Owners may contact Audi customer service at 1-800-253-2834. Volkswagen's number for this recall is 82C1.

# **Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Shiver who may be reached by phone at (202) 366-7401, or by email at sarah.shiver@dot.gov. We look forward to working with you.

Sincerely,

Kareem Habib

Acting Chief, Recall Management Division Office of Defects Investigations

aslan Adul

Enforcement

