

January 29, 2019

Mr. Jim Holliday Technical Information & Warranty Mgr Elgin Sweeper Company Inc. 1300 W. Bartlett Rd Sycamore, IL 60178

Subject: T-Fitting Failure Causing Air Leak/FMVSS 121, 106

Dear Mr. Holliday:

This letter serves to acknowledge Elgin Sweeper Company Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

ELGIN/BROOM BEAR/2015-2018 ELGIN/CROSSWIND/2015-2018 ELGIN/EAGLE/2015-2018 ELGIN/ROAD WIZARD/2015-2018 ELGIN/WHIRLWIND/2015-2018

Mfr's Report Date: December 5, 2018

NHTSA Campaign Number: 18V-865

Components: SERVICE BRAKES, AIR

Potential Number of Units Affected: 1,230

Problem Description:

Elgin Sweeper Company Inc. (Elgin) is recalling certain 2015-2018 Elgin Broom Bear, Crosswind, Eagle, Road Wizard, and Whirl Wind street sweepers. The T-fitting installed on the air brake system may fail, causing air to leak, potentially resulting in the parking brake applying unexpectedly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 121, "Air Brake Systems," and 106, "Brake Hoses."

Consequence:

If the parking brake applies unexpectedly, there would be an increased risk of a crash.

Remedy:

Elgin will notify owners, and dealers will inspect the street sweepers and replace the T-fittings, as necessary, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Elgin customer service at 1-877-342-5374.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150MR 18V-865

NHTSA is missing critical, required information for this safety recall. This information must be supplied through the NHTSA Recalls Portal within 5 working days of confirming its accuracy:

- An identification and description of the risk to motor vehicle safety reasonably related to the defect or noncompliance (49 CFR 573.6 (c)(5)).

- Your company's program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers and dealers, in accordance with § 573.13 of this part. Your company's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by § 573.13 that is not in a general reimbursement plan shall be submitted in your company's report to NHTSA under this section. If your company submits one or more general reimbursement plans, your company shall update each plan every two years, in accordance with § 573.13. Your company's remedy program and reimbursement plans will be available for inspection by the public at NHTSA headquarters (49 CFR 573.6 (c)(8)(i)). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the remedy section of your filing.

- Your company must supply the estimated date(s) for which it will notify owners regarding this safety recall. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefore, and furnish a revised estimate (49 CFR 573.6 (c)(8)(ii)).

- Your company must supply the estimated date(s) for which it will notify dealers and/or distributors regarding this safety recall. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefore, and furnish a revised estimate. (49 CFR 573.6 (c)(8)(ii)).

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

arlan Adul

Kareem Habib Acting Chief, Recall Management Division Office of Defects Investigations Enforcement

