

**Recall Quarterly Report****18V-064**

**Manufacturer Name :** Suzuki Motor of America, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 18V-064 /2A76 to 2A81  
**Recall Subject :** Shifting with High RPMs may cause Chain to Break  
**Owner Notification Beginning Date :** JAN 25, 2018  
**Owner Notification End Date:** JAN 25, 2018



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	OCT 30, 2018	2018-3	3,097	2,835	16	79
2	JUL 24, 2018	2018-2	3,097	2,738	21	1
1	APR 25, 2018	2018-1	3,097	2,074	27	0

This Document Last Updated : OCT 31, 2018

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.