

**Recall Quarterly Report****18V-694**

**Manufacturer Name :** Suzuki Motor of America, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 18V-694 /2A86-2A88  
**Recall Subject :** Fuel Pump O-ring Twisted Causing Fuel Leak  
**Owner Notification Beginning Date :** OCT 31, 2018  
**Owner Notification End Date:** OCT 31, 2018



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	JUL 26, 2019	2019-2	6,928	4,517	90	82
2	APR 30, 2019	2019-1	6,928	3,897	96	82
1	JAN 29, 2019	2018-4	6,928	3,106	93	81

This Document Last Updated : JUL 30, 2019

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.