#### OMB Control No.: 2127-0004

# **Part 573 Safety Recall Report**

## Manufacturer Name : Chrysler (FCA US LLC) Submission Date: OCT 29, 2018 NHTSA Recall No.: 18E-097 Manufacturer Recall No.: UB5

### **Manufacturer Information :**

Manufacturer Name : Chrysler (FCA US LLC) Address: 800 Chrysler Drive CIMS 482-00-91 Auburn Hills MI 48326-2757 Company phone : 1-800-853-1403

### **Population :**

Number of potentially involved : 10 Estimated percentage with defect : 100 %

## **Equipment Information :**

Part No. : Size :	Mopar Floor mat 6ML07TRMAA 17.5" x 25" Floor Mat	
	Some driver floor mats manufactured and sold as aftermarket equipment for use in 2018 model year Jeep Grand Cherokee Street and Racing Technology ("SRT") and Trackhawk vehicles ("Market Vehicles") may exhibit an unacceptable amount of clearance between the mat and the accelerator pedal, when installed in a vehicle. The scope was determined through aftermarket part sales information. The recalled driver floor mats have a profile exhibiting an unacceptable amount of clearance between the mat and the accelerator pedal when installed in a vehicle. Similar driver floor mats not included in this recall exhibit an acceptable amount of clearance between the mat and the pedal. There were 3 pieces of this part number sold.	
Production Dates :	MAY 22, 2017 - JUN 01, 2018	
Part No. : Size : Function :	Mopar Floor Mat 6GA92TRMAA 17.5" x 25" Floor Mat Some driver floor mats manufactured and sold as aftermarket equipment for use in 2018 model year Jeep Grand Cherokee Street and Racing Technology ("SRT") and Trackhawk vehicles ("Market Vehicles") may exhibit an unacceptable amount of clearance between the mat and the accelerator pedal, when installed	
The information contained in this report was submitted pursuant to 49 CFR §573		



## 18E-097

## Part 573 Safety Recall Report

18E-097

Page 2

in a vehicle. The scope was determined through aftermarket part sales information. The recalled driver floor mats have a profile exhibiting an unacceptable amount of clearance between the mat and the accelerator pedal when installed in a vehicle. Similar driver floor mats not included in this recall exhibit an acceptable amount of clearance between the mat and the pedal.

There were 7 pieces of this part number sold.Production Dates :MAY 22, 2017 - JUN 01, 2018

### **Description of Defect :**

	FMVSS 1 : FMVSS 2 :	
Descri	iption of the Cause :	
Identification of Any Warning that can Occur :		NR
Supplier Identification :		
Component Manufacturer		
	Visscher-Caravelle	
Address :	Sisalstraat 85 8281 JK Genemuid	en FOREIGN STATES

Country: Netherlands

The information contained in this report was submitted pursuant to 49 CFR §573

### **Chronology**:

• On September 11, 2018, FCA US LLC ("FCA US") found a VOQ on the NHTSA website from a customer alleging that the accelerator pedal in his 2018 Jeep Grand Cherokee Trackhawk vehicle became stuck under the floor mat on multiple occasions. The VOQ is dated August 24, 2018.

• On September 13, 2018, the FCA US Vehicle Safety and Regulatory Compliance ("VSRC") organization opened an investigation as a result of the VOQ.

• Between September 13, 2018 and October 3, 2018, FCA US VSRC confirmed that the driver floor mats described in this document could exhibit an unacceptable amount of clearance between the mat and the accelerator pedal when installed in the Market Vehicles, and might interfere with and potentially entrap the accelerator pedal.

• As of October 10, 2018, FCA US identified approximately 1 CAIR, 1 VOQ and 1 field report related to this issue.

• As of October 10, 2018, total warranty is 1 at 0.19c/1000.

• As of October 10, 2018, FCA US is unaware of any accidents or injuries potentially related to this issue.

• On October 22, 2018, FCA US determined, through the Vehicle Regulations Committee, to conduct a voluntary equipment safety recall of the affected vehicles.

### **Description of Remedy :**

Description of Remedy Program :	FCA US will conduct a Voluntary Equipment Safety Recall, to replace any floor mats sold aftermarket of the defective design with new ones of a different design.
	FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.
How Remedy Component Differs	
from Recalled Component :	Part Description: Floor Mat Kit Part Number: 6ML07TRMAA, 6GA92TRMAA
	Comment: These floor mats are sold as kits under these part numbers, but only the driver's side floor mat is the subject of this document. The TRM in the part number will be replaced by the color code for each part. The remedy components provide an acceptable amount of clearance to the pedal.
Identify How/When Recall Condition was Corrected in Production :	NR
Recall Schedule :	

Description of Recall Schedule : \*\*10/29/2018: FCA US will notify dealers and begin notifying owners on or about 12/18/2018.

The information contained in this report was submitted pursuant to 49 CFR §573

## **Part 573 Safety Recall Report**

Planned Dealer Notification Date :DEC 18, 2018 - DEC 18, 2018Planned Owner Notification Date :DEC 18, 2018 - DEC 18, 2018

#### **Purchaser Information :**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR Address : NR NR Country : NR Company Phone : NR

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573