OMB Control No.: 2127-0004

Part 573 Safety Recall Report

18E-117

Manufacturer Name: TAP Worldwide, LLC

NHTSA Recall No.: 18E-117

Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: TAP Worldwide, LLC

Address: 400 West Artesia Blvd

Compton CA 90220

Company phone: 999

Population:

Number of potentially involved : 114 Estimated percentage with defect : 100 %

Equipment Information:

Brand / Trade 1: Poison Spyder Customs

Model: Tire Carrier Part No.: 19-62-030TP1

Size: NR Function: NR

Descriptive Information: The subject part is a frame mounted spare tire carrier.

Production Dates: JUN 01, 2018 - DEC 01, 2018

Description of Noncompliance:

Description of the TAP Worldwide, LLC has determined that the subject Poison Spyder Frame

Noncompliance: Mounted Tire Carrier does not comply with FMVSS 108 because the tire carrier

does not provide a license plate lamp or center high-mounted stop light. TAP Worldwide, LLC has also determined that the subject Poison Spyder Frame Mounted Tire Carrier does not comply with FMVSS 111 because the tire carrier

renders the rear view camera inoperable.

FMVSS 1: 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2: 111 - Rearview mirrors

Description of the Safety Risk: An inoperable center high mounted stop lamp may not properly alert

following vehicles that the vehicle is coming to a stop, which increases the risk of crash. Additionally, when reverse gear is selected, the rear camera view would not be available. Because the rear view camera would not be available, if the driver does not check his or her surroundings before

reversing, there is an increased risk of crash.

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

Supplier Identification:

Component Manufacturer

Name: TAP Manufacturing, LLC

Address: 2360 Boswell Rd.

Chula Vista CALIFORNIA 91914

Country: United States

Chronology:

On December 7, 2018, TAP Worldwide, LLC determined that a noncompliance with FMVSS 108 and 111 existed due to interference with the backup camera, license plate lamp, and center high mounted stop lamp.

Description of Remedy:

Description of Remedy Program: TAP Worldwide, LLC will provide replacement Frame Mounted Tire

Carriers that will include the original equipment backup camera and will not interfere with the license plate lamp or center high mounted stop

lamp.

How Remedy Component Differs The replacement Frame Mounted Tire Carrier will not render inoperable from Recalled Component: the backup camera, license plate lamp, or center high mounted stop lamp.

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: Owners and dealers will be notified at the same time, on or before

February 12, 2019.

Planned Dealer Notification Date: FEB 12, 2019 - FEB 12, 2019

Planned Owner Notification Date: NR - NR

Purchaser Information:

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Part 573 Safety Recall Report

18E-117

Page 3

Name: NR

Address: NR

NR

Country: NR

Company Phone: NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573