

Description of the Safety Risk : An inflator rupture may cause metal fragments to pass through the air bag and into the vehicle interior at high speed, which may result in injury or death to vehicle occupants.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : T.K. Holdings, Inc.

Address : 111 Peyer Court
Romeo Michigan 48065

Country : United States

Chronology :

January 2, 2018

Takata submitted equipment defect notifications (18E-001, 18E-002, and 18E-003) to NHTSA that identified a defect in the subject passenger frontal airbag inflators.

January 9, 2018

Based on the determination by Takata that a defect exists in the subject inflators, as set forth in the equipment defect notification (18E-001, 18E-002, and 18E-003) filed by Takata on January 2, 2018, Honda Motor Co., Ltd., determined a safety defect exists in the affected vehicles and decided to conduct a safety recall.

Description of Remedy :

Description of Remedy Program : The owners of all affected vehicles will be contacted by mail and asked to take their vehicle to a Honda or Acura automobile dealer. The dealer will replace the passenger frontal airbag inflator with a new inflator, free of charge.

How Remedy Component Differs from Recalled Component : Passenger's Frontal Airbag Inflator, Passenger's Frontal Airbag Inflator, Part no.: 77820-SCV-A91ZA, 77820-SJC-A92ZB, 06780-SJA-A80

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Owner notification will begin on or about February 12, 2018

Planned Dealer Notification Date : JAN 10, 2018 - NR

Planned Owner Notification Date : FEB 12, 2018 - NR

* NR - Not Reported