

Part 573 Safety Recall Report

18V-087

Manufacturer Name : Jaguar Land Rover North America, LLC**Submission Date :** FEB 08, 2018**NHTSA Recall No. :** 18V-087**Manufacturer Recall No. :** N138**Manufacturer Information :****Population :**

Manufacturer Name : Jaguar Land Rover North America, LLC

Number of potentially involved : 8,211

Address : 555 MACARTHUR BOULEVARD

Estimated percentage with defect : 100 %

MAHWAH NJ 07430

Company phone : 8188500

Vehicle Information :

Vehicle 1 : 2018-2018 Land Rover Range Rover Evoque

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2018 Model Year Range Rover Evoque, Range Rover Velar and Discovery Sport vehicles fitted with 2.0L Gasoline engines, for an under hood gasoline fuel leak. The brazing of the fuel rail end caps is inconsistent and may not provide the design condition so not sealing the fuel rail ends. Fuel vapor and liquid fuel leaks can occur over time. This can lead to a liquid fuel leak into the engine bay.

Production Dates : JUL 21, 2017 - DEC 19, 2017

VIN Range 1 : Begin : SALVC2RX1JH255258 End : SALVP2RX3JH296852 Not sequential

Vehicle 2 : 2018-2018 Land Rover Discovery Sport

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2018 Model Year Range Rover Evoque, Range Rover Velar and Discovery Sport vehicles fitted with 2.0L Gasoline engines, for an under hood gasoline fuel leak. The brazing of the fuel rail end caps is inconsistent and may not provide the design condition so not sealing the fuel rail ends. Fuel vapor and liquid fuel leaks can occur over time. This can lead to a liquid fuel leak into the engine bay.

Production Dates : JUN 19, 2017 - DEC 28, 2017

VIN Range 1 : Begin : SALCR2RX4JH708388 End : SALCR2SX4JH748920 Not sequential

Vehicle 3 : 2018-2018 Land Rover Range Rover Velar

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2018 Model Year Range Rover Evoque, Range Rover Velar and Discovery Sport vehicles fitted with 2.0L Gasoline engines, for an under hood gasoline fuel leak. The brazing of the fuel rail end caps is inconsistent and may not provide the design condition so not sealing the fuel rail ends. Fuel vapor and liquid fuel leaks can occur over time. This can lead to a liquid fuel leak into the engine bay.

Production Dates : APR 26, 2017 - DEC 19, 2017

VIN Range 1 : Begin : SALYB2RX9JA700192 **End :** SALYM2RX8JA745540 Not sequential

Description of Defect :

Description of the Defect : Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2018 Model Year Range Rover Evoque, Range Rover Velar and Discovery Sport vehicles fitted with 2.0L Gasoline engines, for an under hood gasoline fuel leak. The brazing of the fuel rail end caps is inconsistent and may not provide the design condition so not sealing the fuel rail ends. Fuel vapor and liquid fuel leaks can occur over time. This can lead to a liquid fuel leak into the engine bay.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Should leaking fuel come into contact with a sufficiently hot surface there is an increased risk of fire.

Description of the Cause : NR

Identification of Any Warning that can Occur : Fuel odor may be noticed by the driver and they may also observe liquid fuel if the hood is lifted.

Supplier Identification :

Component Manufacturer

Name : Winkelmann SP. Z O.O

Address : NR

Legnica FOREIGN STATES 59-220

Country : Poland

Chronology :

See attached document: N138 - Chronology of Defect_Noncompliance Determination

Description of Remedy :

Description of Remedy Program : Land Rover will notify owners, and authorized repairers will replace the fuel rail. There will be no charge to owners for this repair.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Distribution of owner notification letters will occur on or before March 23, 2018.

Planned Dealer Notification Date : FEB 07, 2018 - FEB 07, 2018

Planned Owner Notification Date : MAR 23, 2018 - MAR 23, 2018

* NR - Not Reported