

Part 573 Safety Recall Report

18V-132

Manufacturer Name : Winnebago Industries, Inc**Submission Date :** MAR 06, 2018**NHTSA Recall No. :** 18V-132**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Winnebago Industries, Inc

Address : PO BOX 152
605 W. Crystal Lake Rd. Forest City IA
50436

Company phone : 1-641-585-3535

Population :

Number of potentially involved : 101

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2019 Winnebago Revel

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The population was determined that all vehicle shipped prior to the hold notice dated 2/22/2018 would be recalled. Those in the field would not have an additional L bracket that is being added to the installation of the luggage rack as of 2/22/2018

Production Dates : AUG 29, 2017 - FEB 21, 2018

VIN Range 1 : Begin : NR End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Roof luggage rack mounting brackets may crack allowing the luggage rack to detached from the roof of the vehicle.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the luggage rack were to detach from the roof of the vehicle during travel it would pose a significant safety risk that may cause property damage, personal injury, potential crash, and death.

Description of the Cause : bracket material not suitable for application

Identification of Any Warning that can Occur : visual identifying cracked or cracking mounting brackets

Supplier Identification :

Component Manufacturer

Name : Summit
Address : 6750 NE 1st Ave.
Altoona IOWA 50009
Country : United States

Chronology :

NR

Description of Remedy :

Description of Remedy Program : The saddle brackets that mount the luggage rack have changed in design as well as the material that the bracket is constructed from. An additional metal L bracket will also be installed to assist in securing the cross members to the luggage rack rails. Winnebago will reimburse our dealers for labor to install the newly designed brackets and hardware thru a reimbursement claim.

How Remedy Component Differs
from Recalled Component : NR

Identify How/When Recall Condition
was Corrected in Production : The recall conditioned was remedied thru a hold notice 868, issued 2/19/2018. All units built after this date were produced with the newly designed brackets and hardware.

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : NR - NR
Planned Owner Notification Date : NR - NR

* NR - Not Reported