

# Part 573 Safety Recall Report

# 18V-146

**Manufacturer Name :** Triple E Recreational Vehicles

**Submission Date :** JUN 13, 2019

**NHTSA Recall No. :** 18V-146

**Manufacturer Recall No. :** CA#8930-1



## Manufacturer Information :

Manufacturer Name : Triple E Recreational Vehicles

Address : PO Box 1230 Winkler MB

Canada 00 R6W 4C4

Company phone : 204-325-4361

## Population :

Number of potentially involved : 752

Estimated percentage with defect : 100 %

## Vehicle Alterer Information :

Vehicle 1 : 2017-2018 UNITY ALL MODELS

Descriptive Information : The OCCC (Occupant & Cargo Carrying Capacity) decal & Tire decal has the incorrect OCCC amount. These decals are indicating more OCCC weight than the actual amount. The OCCC weight has been calculated by a computer generated formula, which was inputted incorrectly. Prior to this it was manually calculated.

Production Dates : JAN 17, 2017 - FEB 23, 2018

Vehicle 2 : 2017-2018 SERENITY S24CB

Descriptive Information : The OCCC (Occupant & Cargo Carrying Capacity) decal & Tire decal has the incorrect OCCC amount. These decals are indicating more OCCC weight than the actual amount. The OCCC weight has been calculated by a computer generated formula, which was inputted incorrectly. Prior to this it was manually calculated.

Production Dates : JAN 17, 2017 - FEB 23, 2018

Vehicle 3 : 2017-2018 WONDER ALL MODELS

Descriptive Information : The OCCC (Occupant & Cargo Carrying Capacity) decal & Tire decal has the incorrect OCCC amount. These decals are indicating more OCCC weight than the actual amount. The OCCC weight has been calculated by a computer generated formula, which was inputted incorrectly. Prior to this it was manually calculated.

Production Dates : JAN 17, 2017 - FEB 23, 2018

## Description of Noncompliance :

Description of the Noncompliance : The OCCC (Occupant & Cargo Carrying Capacity) decal & Tire decal has been calculated incorrectly indicating more OCCC weight than the actual amount.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : As a result, the vehicle could be overloaded, which would result in poor vehicle handling characteristics increasing the risk of a crash causing injury and/or damage to property.

Description of the Cause : The formula to calculate the OCCC was inputted into a computer generated calculation program incorrectly.

Identification of Any Warning that can Occur : N/A

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

## Chronology :

An in-house inspection of the OCCC weight calculation was done and found the calculation formula was incorrect. The in-house inspection was conducted on February 28/2018. There are no field reports or warranty claims at this time.

## Description of Remedy :

Description of Remedy Program : Triple E RV will provide two new OCCC decals and one Tire decal, send to Dealers & Retail Owners with instructions to adhere these three new decals. If the Retail Owners choose to have a servicing center perform the recall, the retail owner will be reimbursed or the servicing center will be paid directly by Triple E RV. The Dealer will submit a warranty claim for the time allotted to perform the recall.

How Remedy Component Differs from Recalled Component : The new decals will have a lower OCCC weight amount. FD-331 OCCC FD-

Identify How/When Recall Condition was Corrected in Production : At this time the IT department has corrected the calculation formula in the program.

## Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : MAR 12, 2018 - MAR 15, 2018

Planned Owner Notification Date : MAR 12, 2018 - MAR 15, 2018

**Purchaser Information :**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name :

Address :

Country :

Company Phone :

\* NR - Not Reported