

Part 573 Safety Recall Report

18V-148

Manufacturer Name : Volkswagen Group of America, Inc.

Submission Date : JUN 28, 2018

NHTSA Recall No. : 18V-148

Manufacturer Recall No. : 69Q9



Manufacturer Information :

Population :

Manufacturer Name : Volkswagen Group of America, Inc.

Number of potentially involved : 234,600

Address : 3800 Hamlin Road
Auburn Hills MI 48326

Estimated percentage with defect : 100 %

Company phone : 1-800-893-5298

Vehicle Information :

Vehicle 1 : 2010-2014 Volkswagen Golf

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : This filing is made in conjunction with a filing in the United States required per the NHTSA Coordinated Remedy Order for Takata, and will provide a final remedy (Takata airbag inflator) to all Volkswagen vehicles that were originally part of VW recall 69M9 (NHTSA 16V-078).
The airbags that will be installed in this remedy contain a GuNi (Guanidine Nitrate) propellant in the inflator. The driver frontal airbag part numbers that will be installed are 3C0898201J, 3C8898201C, 3C0898201H, 3C8898201B and are considered a final repair.

Production Dates : MAY 19, 2009 - OCT 25, 2013

VIN Range 1 : Begin : WVWMM7AJ7AW000338 End : WVWNM7AJ0EW011935 ☒ Not sequential

Vehicle 2 : 2010-2011 Volkswagen Eos

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : This filing is made in conjunction with a filing in the United States required per the NHTSA Coordinated Remedy Order for Takata, and will provide a final remedy (Takata airbag inflator) to all Volkswagen vehicles that were originally part of VW recall 69M9 (NHTSA 16V-078).
The airbags that will be installed in this remedy contain a GuNi (Guanidine Nitrate) propellant in the inflator. The driver frontal airbag part numbers that will be installed are 3C0898201J, 3C8898201C, 3C0898201H, 3C8898201B and are considered a final repair.

Production Dates : JUN 04, 2009 - JUL 27, 2010

VIN Range 1 : Begin : WVWAA7AHXAV004267 End : WVWAW7AH1BV004564 ☒ Not sequential

Vehicle 3 : 2007-2010 Volkswagen Passat Sedan

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : This filing is made in conjunction with a filing in the United States required per the NHTSA Coordinated Remedy Order for Takata, and will provide a final remedy (Takata airbag inflator) to all Volkswagen vehicles that were originally part of VW recall 69M9 (NHTSA 16V-078).
The airbags that will be installed in this remedy contain a GuNi (Guanidine Nitrate) propellant in the inflator. The driver frontal airbag part numbers that will be installed are 3C0898201J, 3C8898201C, 3C0898201H, 3C8898201B and are considered a final repair.

Production Dates : NOV 02, 2006 - MAY 27, 2009

VIN Range 1 : Begin : WVWAU73C57P083000 End : WVWJK7AN7AP000054 ☒ Not sequential

Vehicle 4 : 2007-2010 Volkswagen Passat Wagon

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : This filing is made in conjunction with a filing in the United States required per the NHTSA Coordinated Remedy Order for Takata, and will provide a final remedy (Takata airbag inflator) to all Volkswagen vehicles that were originally part of VW recall 69M9 (NHTSA 16V-078).
The airbags that will be installed in this remedy contain a GuNi (Guanidine Nitrate) propellant in the inflator. The driver frontal airbag part numbers that will be installed are 3C0898201J, 3C8898201C, 3C0898201H, 3C8898201B and are considered a final repair.

Production Dates : NOV 02, 2006 - MAY 13, 2009

VIN Range 1 : Begin : WVWLK73C17E111434 End : WVW XK7AN0AE003075 ☒ Not sequential

Vehicle 5 : 2007-2008 Volkswagen Passat Sedan

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : This filing is made in conjunction with a filing in the United States required per the NHTSA Coordinated Remedy Order for Takata, and will provide a final remedy (Takata airbag inflator) to all Volkswagen vehicles that were originally part of VW recall 69M9 (NHTSA 16V-078).
The airbags that will be installed in this remedy contain a GuNi (Guanidine Nitrate) propellant in the inflator. The driver frontal airbag part numbers that will be installed are 3C0898201J, 3C8898201C, 3C0898201H, 3C8898201B and are considered a final

repair.

Production Dates : DEC 19, 2006 - MAY 25, 2008

VIN Range 1 : Begin : WVWAK73C07E142648 End : WVWJK73C18E252853 ☒ Not sequential

Vehicle 6 : 2013-2014 Volkswagen CC

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : This filing is made in conjunction with a filing in the United States required per the NHTSA Coordinated Remedy Order for Takata, and will provide a final remedy (Takata airbag inflator) to all Volkswagen vehicles that were originally part of VW recall 69M9 (NHTSA 16V-078).
The airbags that will be installed in this remedy contain a GuNi (Guanidine Nitrate) propellant in the inflator. The driver frontal airbag part numbers that will be installed are 3C0898201J, 3C8898201C, 3C0898201H, 3C8898201B and are considered a final repair.

Production Dates : JAN 19, 2012 - MAY 27, 2014

VIN Range 1 : Begin : WVWAP7AN9DE500024 End : WVWAP7AN4EE541047 ☒ Not sequential

Vehicle 7 : 2009-2012 Volkswagen CC

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : This filing is made in conjunction with a filing in the United States required per the NHTSA Coordinated Remedy Order for Takata, and will provide a final remedy (Takata airbag inflator) to all Volkswagen vehicles that were originally part of VW recall 69M9 (NHTSA 16V-078).
The airbags that will be installed in this remedy contain a GuNi (Guanidine Nitrate) propellant in the inflator. The driver frontal airbag part numbers that will be installed are 3C0898201J, 3C8898201C, 3C0898201H, 3C8898201B and are considered a final repair.

Production Dates : JUN 26, 2008 - DEC 02, 2011

VIN Range 1 : Begin : WVWDL93CX9E508060 End : WVWNP7AN2CE551221 ☒ Not sequential

Vehicle 8 : 2010-2014 Volkswagen Golf

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : This filing is made in conjunction with a filing in the United States required per the NHTSA Coordinated Remedy Order for Takata, and will provide a final remedy (Takata airbag inflator) to all Volkswagen vehicles that were originally part of VW recall 69M9 (NHTSA 16V-078).
The airbags that will be installed in this remedy contain a GuNi (Guanidine Nitrate)

propellant in the inflator. The driver frontal airbag part numbers that will be installed are 3C0898201J, 3C8898201C, 3C0898201H, 3C8898201B and are considered a final repair.

Amendment 06/28/2018

Production Dates : MAR 17, 2009 - OCT 30, 2013

VIN Range 1 : Begin : WVWAB7AJ5AW000069 End : WVWDB7AJ0EW011998 ☒ Not sequential

Vehicle 9 : 2013-2014 Volkswagen CC

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : This filing is made in conjunction with a filing in the United States required per the NHTSA Coordinated Remedy Order for Takata, and will provide a final remedy (Takata airbag inflator) to all Volkswagen vehicles that were originally part of VW recall 69M9 (NHTSA 16V-078).
The airbags that will be installed in this remedy contain a GuNi (Guanidine Nitrate) propellant in the inflator. The driver frontal airbag part numbers that will be installed are 3C0898201J, 3C8898201C, 3C0898201H, 3C8898201B and are considered a final repair.

Amendment 06/28/2018

Production Dates : JAN 19, 2012 - JUN 04, 2014

VIN Range 1 : Begin : WVWRP7AN0DE500027 End : WVWBP7AN8EE541069 ☒ Not sequential

Vehicle 10 : 2010-2010 Volkswagen Passat Sedan

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : This filing is made in conjunction with a filing in the United States required per the NHTSA Coordinated Remedy Order for Takata, and will provide a final remedy (Takata airbag inflator) to all Volkswagen vehicles that were originally part of VW recall 69M9 (NHTSA 16V-078).
The airbags that will be installed in this remedy contain a GuNi (Guanidine Nitrate) propellant in the inflator. The driver frontal airbag part numbers that will be installed are 3C0898201J, 3C8898201C, 3C0898201H, 3C8898201B and are considered a final repair.

Amendment 06/28/2018

Production Dates : SEP 21, 2009 - JUN 01, 2010

VIN Range 1 : Begin : WVWJL7AN4AE046904 End : WVWJM7ANXAE170141 ☒ Not sequential

Vehicle 11 : 2010-2010 Volkswagen Passat Wagon

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : This filing is made in conjunction with a filing in the United States required per the NHTSA Coordinated Remedy Order for Takata, and will provide a final remedy (Takata airbag inflator) to all Volkswagen vehicles that were originally part of VW recall 69M9 (NHTSA 16V-078).
The airbags that will be installed in this remedy contain a GuNi (Guanidine Nitrate) propellant in the inflator. The driver frontal airbag part numbers that will be installed are 3C0898201J, 3C8898201C, 3C0898201H, 3C8898201B and are considered a final repair.

Amendment 06/28/2018

Production Dates : MAY 13, 2009 - JUN 01, 2010

VIN Range 1 : Begin : WVWXX7AN8AE003065 End : WVWXM7AN6AE170101 ☒ Not sequential

Vehicle 12 : 2010-2010 Volkswagen Passat Sedan

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : This filing is made in conjunction with a filing in the United States required per the NHTSA Coordinated Remedy Order for Takata, and will provide a final remedy (Takata airbag inflator) to all Volkswagen vehicles that were originally part of VW recall 69M9 (NHTSA 16V-078).
The airbags that will be installed in this remedy contain a GuNi (Guanidine Nitrate) propellant in the inflator. The driver frontal airbag part numbers that will be installed are 3C0898201J, 3C8898201C, 3C0898201H, 3C8898201B and are considered a final repair.

Amendment 06/28/2018

Production Dates : SEP 30, 2009 - MAY 28, 2010

VIN Range 1 : Begin : WVWJL7AN6AP019756 End : WVWJK7ANXAP055890 ☒ Not sequential

Vehicle 13 : 2010-2011 Volkswagen Eos

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : This filing is made in conjunction with a filing in the United States required per the NHTSA Coordinated Remedy Order for Takata, and will provide a final remedy (Takata airbag inflator) to all Volkswagen vehicles that were originally part of VW recall 69M9 (NHTSA 16V-078).
The airbags that will be installed in this remedy contain a GuNi (Guanidine Nitrate) propellant in the inflator. The driver frontal airbag part numbers that will be installed are 3C0898201J, 3C8898201C, 3C0898201H, 3C8898201B and are considered a final repair.

Amendment 06/28/2018

Production Dates : APR 29, 2009 - AUG 14, 2010

VIN Range 1 : Begin : WVWBA7AH6AV003847 End : WVWFW7AH3BV005544 ☒ Not sequential

Vehicle 14 : 2010-2012 Volkswagen CC

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : This filing is made in conjunction with a filing in the United States required per the NHTSA Coordinated Remedy Order for Takata, and will provide a final remedy (Takata airbag inflator) to all Volkswagen vehicles that were originally part of VW recall 69M9 (NHTSA 16V-078).
The airbags that will be installed in this remedy contain a GuNi (Guanidine Nitrate) propellant in the inflator. The driver frontal airbag part numbers that will be installed are 3C0898201J, 3C8898201C, 3C0898201H, 3C8898201B and are considered a final repair.

Amendment 06/28/2018

Production Dates : MAY 14, 2008 - DEC 24, 2011

VIN Range 1 : Begin : WVWGU73C59E502245 End : WVWHP7AN0CE553420 ☒ Not sequential

Vehicle 15 : 2012-2014 Volkswagen Eos

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : This filing is made in conjunction with a filing in the United States required per the NHTSA Coordinated Remedy Order for Takata, and will provide a final remedy (Takata airbag inflator) to all Volkswagen vehicles that were originally part of VW recall 69M9 (NHTSA 16V-078).
The airbags that will be installed in this remedy contain a GuNi (Guanidine Nitrate) propellant in the inflator. The driver frontal airbag part numbers that will be installed are 3C0898201J, 3C8898201C, 3C0898201H, 3C8898201B and are considered a final repair.

Amendment 06/28/2018

Production Dates : DEC 02, 2010 - MAY 31, 2014

VIN Range 1 : Begin : WVWBW7AH7CV000010 End : WVWBW8AH1EV007351 ☒ Not sequential

Description of Defect :

Description of the Defect : The driver frontal airbag inflator could potentially rupture (due to propellant degradation occurring after long-term exposure to absolute high humidity and temperature cycling) if the vehicle is involved in a crash where the passenger frontal airbag is designed to deploy. In the event of an inflator rupture, in very rare cases metal fragments could pass through the airbag cushion material, which may result in serious injury or death to vehicle occupants.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : In the event of an inflator rupture, in very rare cases metal fragments could pass through the airbag cushion material, which may result in serious injury or death to vehicle occupants.

Description of the Cause : As reported by Takata: The propellant wafers in some of the subject inflators may degrade over time, which could lead to over-aggressive combustion in the event the air bag is activated. Overly aggressive combustion creates excessive internal pressure when the inflator is activated, which may cause the inflator body to rupture. Based upon Takata's investigation to date, the potential for such ruptures occurs in some of the subject inflators after several years of exposure to persistent conditions of high absolute humidity, high temperatures, and high temperature cycling. The potential for rupture may also be influenced by other factors, including the specific vehicle environment, the inflator and propellant configuration, and manufacturing variability.

Identification of Any Warning NR
that can Occur :

Supplier Identification :

Component Manufacturer

Name : Takata AG

Address : Bahnweg 1
Aschaffenburg FOREIGN STATES 63743

Country : Germany

Chronology :

"This filing is made as required per the NHTSA Coordinated Remedy Order.
Date of determination: March 01, 2018."

Description of Remedy :

Description of Remedy Program : Owners will be notified by mail and instructed to take their vehicle to an authorized Volkswagen dealer to have their driver frontal airbag inflator replaced free of charge. Volkswagen will cooperate with NHTSA to prioritize and stagger vehicle repairs by joining NHTSA's coordinated remedy program. Volkswagen is excluding reimbursement for costs associated with replacement of airbag inflators.

How Remedy Component Differs from Recalled Component : Remedy components are not ammonium-nitrate based accellerant airbag inflators.

Identify How/When Recall Condition was Corrected in Production : N/A

Recall Schedule :

Description of Recall Schedule : Volkswagen will follow the established NHTSA rollout for vehicles affected by this recall.

Owners of the original vehicle population identified under this recall were notified on 3/16 - 3/19/2018

Owners of additional vehicles included with the amendment dated June 28, 2018 will be notified beginning on July 03, 2018.

Planned Dealer Notification Date : MAR 15, 2018 - MAR 15, 2018

Planned Owner Notification Date : MAR 15, 2018 - JUL 03, 2018

* NR - Not Reported