

Part 573 Safety Recall Report

18V-175

Manufacturer Name : Pagani Automobili SpA**Submission Date :** MAR 27, 2018**NHTSA Recall No. :** 18V-175**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Pagani Automobili SpA

Address : Via dell'Artigianato, 5

San Cesario sul Panaro 00 41018

Company phone : 0594739201

Population :

Number of potentially involved : 16

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2017-2017 Pagani Huayra Coupe BC and Huayra Roadster

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : All MY 2017 Pagani Huayra Coupe BC and Huayra Roadster in the production date range.

Production Dates : OCT 18, 2016 - AUG 01, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : There is the possibility that, due to a bug in the battery management software, the 12Vcc battery fails to provide enough power to the car.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : There is the possibility that the engine cannot be started or that the engine stops when it is in the idle. Pagani does not know of any cases of personal injury or death arising from the defect. Nevertheless, to minimize the risk of a serious incident, Pagani is taking the recall action.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Reduce Carbon Energy Develop Co.,Ltd.
Address : No.55, Sec. 3, Jiayuan Rd., Shulin Dist.
New Taipei City FOREIGN STATES
Country : Taiwan, Province of China

Chronology :

On March 8th 2018 Pagani determined that 3 different battery fails, registered during testing, came from a software bug in the battery management system, an hardware component included in the battery itself. Working with the battery manufacturer (Reduce Carbon Energy Develop Co.,Ltd.), it was possible to confirm the fail cause and to determine that there was a risk that the engine cannot be started or that the engine stops when it is in the idle.
Based on this, Pagani determined on March 14th 2018, that a recall was necessary.

Description of Remedy :

Description of Remedy Program : Pagani Automobili SpA will provide notice to all customers and dealers to inform them about the safety defect. Pagani has determined that to change the battery, with a new one that has a new battery management software, is an effective remedy to the issue. This program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addresses by the recall within a reasonable time in advance of the notification of owners, purchasers an dealers.

How Remedy Component Differs from Recalled Component : The Pagani internal registration allow to trace the battery fixed through its SN.

Identify How/When Recall Condition was Corrected in Production : The problem was solved changing the battery management software in all the batteries in production line and in the batteries stored in warehouse.

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : NR - NR
Planned Owner Notification Date : NR - NR

* NR - Not Reported