OMB Control No.: 2127-0004

Part 573 Safety Recall Report

18V-219

Manufacturer Name: Newmar Corporation

Submission Date: APR 05, 2018 NHTSA Recall No.: 18V-219 Manufacturer Recall No.: 18V-194



Manufacturer Information:

Manufacturer Name: Newmar Corporation

Address: 355 North Delaware Street

PO Box 30 Nappanee IN 46550

7 9 201 00 1 tappanee 1

Company phone: 574-773-7791

Population:

Number of potentially involved : 72Estimated percentage with defect : 100%

Vehicle Information:

Vehicle 1: 2018-2019 Newmar New Aire

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : Power Train : NR

Descriptive Information : On certain motorhomes built on a Freightliner chassis, an incorrect valve stem

stabilizer may have been used on the single drive axle. This could result in the incorrect stabilizer to become dislodged from the wheel and allow the valve stem extension for the inner wheel to contact the outer wheel, potentially causing damage to the valve stem. If the valve stem were to be damaged, it could cause a loss of air pressure in the inner tire, which may overload the outer tire and increase the risk of a crash causing injury and/or damage to property. Correction: Daimler Trucks North America authorized service facilities will inspect and replace the inner wheel valve

stem stabilizer as necessary.

Production Dates: JAN 27, 2017 - MAR 07, 2018

VIN Range 1 : Begin : NR End : NR Not sequential

Description of Defect:

Description of the Defect: an incorrect valve stem stabilizer may have been used on the single drive axle.

This could result in the incorrect stabilizer to become dislodged from the wheel and allow the valve stem extension for the inner wheel to contact the outer

wheel, potentially causing damage to the valve stem.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: This could result in the incorrect stabilizer to become dislodged from the

wheel and allow the valve stem extension for the inner wheel to contact the outer wheel, potentially causing damage to the valve stem. If the valve stem were to be damaged, it could cause a loss of air pressure in the inner tire, which may overload the outer tire and increase the risk of a crash causing

injury and/or damage to property.

Description of the Cause: an incorrect valve stem stabilizer may have been used on the single drive axle.

Identification of Any Warning NR

that can Occur:

Supplier Identification:

Component Manufacturer

Name: Daimler Trucks North America

Address: P.O. Box 3849

Portland OREGON 97208

Country: United States

Chronology:

On 3/29/2018, Daimler Trucks North America gave notice to Newmar of a potential defect. On 4/5/2018, Newmar is giving notice of a recall on Newmar motor-homes.

Description of Remedy:

Description of Remedy Program: Daimler Trucks North America authorized service facilities will inspect

and replace the inner wheel valve stem stabilizer as necessary.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: Newmar will send out customer/dealer letters on or before 06/04/2018.

Planned Dealer Notification Date : JUN 04, 2018 - JUN 04, 2018 Planned Owner Notification Date : JUN 04, 2018 - JUN 04, 2018

* NR - Not Reported